

RES 20-1808(9-77)

93969

STATE OF WASHINGTON
DEPARTMENT OF NATURAL RESOURCES
BUREAU OF SURVEYS AND MAPS

3000-3/4 PAGE 20

Also see Feb 1-82

See. No. 1. 3.

LAND CORNER RECORD

Skamania

County

Corner Code No. E - 13

T. 3 N. R. 6 East, W.M.

Segregated Surveys:

Name: N/A

Corner No.: N/A

DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

Originally set by 1903 G.L.O. survey.

No restoration found.

2. Description of Evidence Found:

4 Bearing Tree stump pattern:

1 - 20" Fir B.T. stump at S73 30'E., 20.46 feet from corner location.
1 - 30" Fir B.T. stump at N 55 30'E., 21.12 feet from corner location.
1-28" Fir B.T. stump at N.10 W., 13.86 feet from corner location.
1-30" Hemlock B.T. stump at S.32 W., 23.76 feet from corner location.
No markings were found on any of above stumps.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 600.20. Page No. 30 Date of work 17 Sept. '80

Set 3" cylindrical D.N.R.
concrete monument with
stamped brass cap 4" above
ground on hillside to North,
Northwest and is approx.
110 feet north of ridge top.

See sketch on back.



Washington Plane Coordinates: South Zone, Y 162, 136.51, X 1, 600, 836.63

3rd Order Accuracy. Derived From: USC & GS "Mowich" and USC & GS

"Lookout Mtn. RM=1"

Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or
under my direction in compliance with the provisions of Chapter
50, Laws of 1973. Date May 11, 1982

Signature

11977

Certificate No.

93969



AUDITOR'S CERTIFICATE

Filed for record this 7 day of May 1982 at M. In
Book 376 of *Washington State Department of Natural Resources* at page 20 at the request of
Washington State Department of Natural Resources.

County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2),
Chapter 50, Laws of 1973.

GLD. 1903

NORTH

77.80 top of ascent, BRS. E1W, 0' ELEV. ID
80.00 SOFT DESCENT

SET LARCH POST FOR $\frac{4}{3}$ 110

END 30" FIR N5530E 32 LKS

" 18" " S73-30E 31 LKS

" 30" HEM. S32W 36 LKS

" 28" FIR N104-15W 21 LKS

N.W. CORNER, S10. 7 IN PLS

FOUND


4 STUMP PATTERNS
NO SERVICE

9-17-80

WAIFD
GOFL 71
ERIE 1000
1980

30

TBN
= 4153
59519
R.16E
1980



CORNER IS A 3" CYL. DMR. SERVICE. HIGH
WERNES CAP. COR. 4 1/2" ON 1 1/2" ELEV.
SCOPING TO N.W. IS 7.100' 1/2' ID
OF RIDGE TOP
CAP IS 4" ABOVE GROUND
ALL BT'S WERE DEAD WHEN SERVICED
ALL WERE FINED SNAGS WHEN FOUND