

# LAND CORNER RECORD

Okamania

County

T 7 N, R 6E, W.M.

Corner Code No. G-9

Segregated Surveys:

Name: One-quarter corner

Corner No.:

DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

## 1. History of Corner Establishment and Subsequent Restoration:

This corner was originally set by Deputy Lewis D.W. Shelton in July 1899, & Oct.-Dec. 1900 under Contract No. 552.

Re-aumented by Floyd A. Brooks, Cadastral Surveyor in Oct. & Nov. 1961.

Set Wh. Fir post.

Set Iron post with Brass cap.

Scribed 30" Hemlock N183/4E-27 lks..  
6" Wh. Fir N253/4W-16 lks..

Scribed 8" Fir S56E-22 1/2 lks..  
12" Wh. Fir N24W-58 lks..

## 2. Description of Evidence Found:

BIM 2 1/2" Iron post with Brass cap.

Orig. 30" now 4" Hemlock stump N183/4E-27 lks. scribing visible on unhealed blaze.  
Brooks 8" Fir now 12" Noble Fir N56E-22 1/2 lks. scribing visible on partially healed blaze.

## 3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 2 Page No. 2 Date of work June 1, 1962

New Bearing Tree:

10" D-Fir N53W, 14.0 ft. scribed 1/3" upper blaze and a lower blaze scribed BT and with a 3/4" Brass disk stamped DLS 1633.

Set guard post South with sign 54-4 only.

Nailed 54-4 and BT signs to BT's and painted band and blazes red.



Washington Plane Coordinates: Zone, Y

Order Accuracy. Derived From:


Pin Pointed on Photo No. Date Located at

### SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date

*Larry D. Bishop*  
Signature

16337  
Certificate No.



### AUDITOR'S CERTIFICATE

Filed for record this 13th day of July 1962 at 12:30 P.M. In Book 76 of RECORDS at page 18 at the request of

LARRY D. BISHOP SURVEYOR

*J.M. Olson*  
County Auditor