

94734

LAND CORNER RECORD

T. 7 N, R. 6E, W.M. Shanania County A-15
 Segregated Surveys: Corner Code No. A-15
 Name: One-quarter corner Corner No.: _____
 DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

This corner was originally set by Deputy Lewis D.W. Shelton in July 1999, & Oct.-Dec. 1900 under Contract No. 552. Remonumented by Floyd A. Broods, Cadastral Surveyor in Oct. & Nov. 1961.
 Set Wh. Fir post. Set BLM Iron post with Brass cap.
 Scribed 22" Fir N523/4E-50 lks.. Scribed 14" Wh. Fir N6W-24 lks..
 36" Cedar S61W-31 lks..

2. Description of Evidence Found:

BLM Iron post with Brass cap.
 Orig. 36" now 45" sawed Cedar stump S61W-31 lks. rotted blaze.
 Orig. 22" now 32" sawed Fir stump N523/4E-50 lks.-healed blaze.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 6 Page No. 5 Date of work July 1982

New Bearing Trees:
 5" D-Fir N10W, 7.3 ft. scribed 1/334 upper blaze and a lower blaze scribed BT and with a 3/4" brass disk stamped PLS 16337.
 5" D-Fir S2E, 11.0 ft. scribed 1/33 upper blaze and a lower blaze scribed BT and with a 3/4" Brass disk stamped PLS 16337.
 Set guard post Northwest with sign 54-4 only.
 Nailed 54-4 and BT signs to BT's and painted band and blazes red.



Washington Plane Coordinates: _____ Zone, Y _____, X _____
 Order Accuracy. Derived From: _____
 Pin Pointed on Photo No. _____ Date _____ Located at _____

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date JULY 30, 1982
 Signature Larry D. Bishop Certificate No. 16337



AUDITOR'S CERTIFICATE

Filed for record this 14 day of Sept. 1982 at 1:30 M. In Book 7-6 of Monuments at page 22, at the request of Larry D. Bishop
Larry M. Olson
 County Auditor