

94745

LAND CORNER RECORD

T 7 N, R 6E, W.M. Skamania County Corner Code No. C-13

Name: One-quarter corner Corner No.: DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

This corner was originally set by Deputy Lewis D.W. Shelton in July 1899, & Oct.-Dec. 1900 under Contract No. 552.

Set Fir post.

Scribed 18" Cedar S30 1/2 E-34 lks..

26" Cedar N33W-21 lks..

40" Fir line tree South 17 lks. marked 2 notches N&S.

2. Description of Evidence Found:

Orig. 18" now 20" sawed Cedar stump S30 1/2 E-34 lks.-face burned out.

Orig. 26" now 24" sawed burned Cedar stump N33W-21 lks.-face burned out.

40" D-Fir line tree now 54" sawed D-Fir stump South 17 lks..

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 6 Page No. 6 Date of work July 1982

Set 2 1/2"x30" Aluminum pipe with a 2 1/2" Aluminum cap in a mound of stone.

Chisled XBO on face of rock bluff N36E, 14.40 ft.(measure to center of X).

Set guard post South with sign 54-4 only.

Nailed 54-4 and BT signs to BT's and painted band and blazes red.

Nailed 54-4 sign & painted band on line tree stump.

No live tree or other bearing object available in Sec. 4.

Marked: T.7N R.6E S4 | S3 1982 PLS 16337

Washington Plane Coordinates: Zone, Y

Order Accuracy. Derived From:

Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date AUG. 4, 1982

Signature Larry D. Bishop Certificate No. 16337



AUDITOR'S CERTIFICATE

Filed for record this 1st day of Sept. 1982 at 1:30 P.M. In Book 7/6 of Monuments at page 33 at the request of

Signature Larry M. Olson County Auditor