

94748

LAND CORNER RECORD

T. 7 N, R. 6E, W.M. Skamania County
Segregated Surveys: Corner Code No. D-25

Name: One-sixteenth corner Corner No.:
DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

N/A

2. Description of Evidence Found:

N/A

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 6 Page No. 17 Date of work Aug. 1982

Set $2\frac{1}{2}$ "x30" Aluminum pipe with a $2\frac{1}{2}$ " Aluminum cap.	Marked:
New Bearing Trees:	
18" Hemlock S1W, 12.2 ft. scribed S1/16S1 upper blaze and a lower blaze scribed BT and with a $3/4$ " Brass disk stamped PLS 16337.	T.7N R.7E R.6E S1/16
14" Hemlock S16E, 57.2 ft. scribed S1/16S6 upper blaze and a lower blaze scribed BT and with a $3/4$ " Brass disk stamped PLS 16337.	S1 S6 1982 PLS 16337

Set guard posts North and West with sign 54-4 and BM 102 decals. Nailed 5'-9 and BT signs to BT's and painted band and blazes red.

Washington Plane Coordinates: _____ Zone, Y _____
Order Accuracy. Derived From: _____

Pin Pointed on Photo No. _____ Date _____ Located at _____

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date 8/27/82

Signature Larry D. Bishop Certificate No. 16337



AUDITOR'S CERTIFICATE

Filed for record this 14 day of Sept 1982 at 1:30 P.M. In Book 76 of Monuments at page 36 at the request of

Signature Larry D. Bishop
Signature Mary M. Olson County Auditor