

### LAND CORNER RECORD

T. 7 N, R. 6E, W.M. Skamania County  
 Segregated Surveys: Corner Code No. N-19  
 Name: One-quarter corner Corner No.: \_\_\_\_\_  
DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:  
 This corner was originally set by Deputy Lewis D.M. Shelton in July 1899, & Oct.-Dec. 1900 under Contract No. 552. Remonumented by Floyd A. Brooks, Cadastral Surveyor in Oct. & Nov. 1961.  
 Set Hemlock post. Set 2" Iron post with Brass cap.  
 Scribed 4 1/2" Hemlock N154-17 lks.. Scribed 15" Hemlock N124E-38 lks..  
 10" Yew S54E-21 lks.. Wh. Fir S82E-45 lks..

2. Description of Evidence Found:  
 BIN 2" Iron pipe with a 3" Brass cap.  
 Orig. 10" now 16" Yew scribing visible S54E, 15.7 ft..  
 Brooks 9" now 16" Wh. Fir snag S82E-45 lks. healed blaze.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 5 Page No. 7 Date of work July 1982

New Bearing Tree:  
 9" Cedar N52E, 213.2 ft. scribed 7/8" upper blaze and a lower blaze scribed BT and with a 5/4" Brass disk stamped BIN 16337.  
 Painted red band and blaze red on BT-nailed sign 54-4 and BT signs to BT's.  
 Set guard post West with sign 54-4 and LN 102 decal.

Washington Plane Coordinates: \_\_\_\_\_ Zone, Y \_\_\_\_\_, X \_\_\_\_\_  
 Order Accuracy. Derived From: \_\_\_\_\_  
 Pin Pointed on Photo No. \_\_\_\_\_ Date \_\_\_\_\_ Located at \_\_\_\_\_

#### SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date July 22, 1982  
 Signature Larry D. Bishop Certificate No. 16337



#### AUDITOR'S CERTIFICATE

Filed for record this 14 day of Sept 1982 at 1:30 P. M. In Book 7/6 of monuments at page 53 at the request of Larry D. Bishop  
 County Auditor Larry M. Wood