

RES 20-1808(9-77)

95295

LAND CORNER RECORD

SKAMANIA County

T 4 N. R 9 E W.M.
Segregated Surveys:

Corner Code No. W-21

Name: N 116

Corner No.:

DLC, HFS, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

RON DIXON SET COR FOR BROUGHTON LUMBER CO. IN MID 1960'S.



2. Description of Evidence Found:

FOUND DIXON'S 2 1/2" WATER PIPE WITH CAP BEARING N 0-S8 39 W A DISTANCE OF 38.83' FROM OUR SET POINT.

Dir.
Sect.
Div.
No.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 2 Page No. 16 Date of work 12/82

SET A 2 1/2" x 30" ALLUM. PIPE WITH A 2 1/2" ALLUM. CAP.



Washington Plane Coordinates: Zone, Y, X
Order Accuracy. Derived From:

Pin Pointed on Photo No. Date Located at.

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date 1-6-1983

Signature: *Rosa Gaylord*

18731
Certificate No.

95295



AUDITOR'S CERTIFICATE

Filed for record this 19 day of April 1983 at 10:40 AM. In Book 419 of *Washington* at page 35 at the request of

Rosa Gaylord

Hary M. Adams
County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.