

95298

LAND CORNER RECORD

SKAMANIA

County

T 4 N, R 9 E . W.M.

Corner Code No. X-19

Segregated Surveys:

Name: CENTER ONE-QUARTER

Corner No.:

DLC, RES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

BON DIXON SET COR. FOR BROUGHTON LUMBER COMPANY IN MID 1960'S.



2. Description of Evidence Found:

FOUND A 3/4" PIPE IN MOUND OF ROCK BEARING N 31-59-49 IN A DISTANCE OF 16.61' FROM OUR SET POINT.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No.

8 Page No. 4 Date of work 12/82

SET A 2 1/2" X 30" ALLUM. PIPE WITH A 2 1/2" ALLUM. CAP.



Washington Plane Coordinates: Zone, Y X
Order Accuracy. Derived From:

Pin Picked on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date 1-6-1983

Signature *Ray O. Gaylord*

18731
Certificate No.
95298



AUDITOR'S CERTIFICATE

Filed for record this 19 day of Jan 1983 at 10:46 AM. In Book 419 of Filaments at page 38 at the request of

Ray O. Gaylord
Cheryl M. Olson
County Auditor