

95301

LAND CORNER RECORD

SKAMANIA

County

T. 4 N. R. 9 E. W.M.  
Segregated Surveys:

Corner Code No. Y-21

Name: S 1116

Corner No.:

D.L.C. B.F.S., Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

130N DIXON SET COR. FOR BROUGHTON LUMBER CO. IN MID 1960'S.




2. Description of Evidence Found:

FOUND DIXON 1 1/2" PIPE WITH CAP BEARING N 69-40-27E A DISTANCE OF 23.77' FROM OUR SET POINT.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No.

7 Page No. 11 Date of work 12/82

SET A 2 1/2" x 30" ALLUM. PIPE WITH A 2 1/2" ALLUM. CAP. COR. FELL AT BASE OF DOUG FIR



Washington Plane Coordinates: Zone, Y X  
Order Accuracy. Derived From:

Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date 1-6-1983

Signature Roy G. Dayland

18131 Certificate No.

95301



AUDITOR'S CERTIFICATE

Filed for record this 19 day of Jan 1983 at 10:40 A.M. In Book 419 of Skamania at page 41 at the request of

Roy G. Dayland

Signature Gary M. Olson  
County Auditor