

LH LAWSON
 LAND SURVEYING
 LICENSED WASHINGTON AND OREGON
 (206) 256-8008

JOHN G. LAWSON
 Registered Professional Land Surveyor
 Registered Professional Engineer

Y-Plaza
 14612 A 4th Plain Rd
 Vancouver, WA 98662

LAND CORNER RECORD

T 3 N, R 8 E, W.M.; Skamania county

Corner Code Number: L-21

Page 1 of 1

Name: One-quarter corner common to Sections 13 and 14 ; Corner
 DLC, HES Mining Claim, Indian Allotment, Federal Reserve, Townsite ; Number L-21

1. History of Corner Establishment and Subsequent Restoration; description of Evidence Found:

There is no evidence left of this corner. This area has burned very hot and the small trees called for in the GLO notes have been destroyed. We set this corner by single-proportionate measurement. DNR concrete monument bears South 28° 38' West, 25.72 feet.

2. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record.

LAWSON LAND SURVEYING Job # 25 - 82 - 150308 ; Date of Work: June, 1982

Set brass cap in 1 inch galvanized Iron Pipe 3 feet long and referenced as follows:

30-inch Douglas Fir, North 30° East, 28.9 feet, scribed "S 13 W 1/2 BT"

9-inch Douglas Fir, South 41° West, 16.1 feet, scribed "S 14 E 1/2 BT"

Washington Plane Coordinates: _____ Zone, Y _____, X _____
 _____ Order of Accuracy. Derived from: _____

Pin Pointed on Photo No. _____ Date _____ Located at _____

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973.

Signature John G. Lawson Date Oct 1982
 Certificate Number 11989



AUDITOR'S CERTIFICATE

Filed for record this 3RD day of Dec, 1982 at 3:40 P.M.
 In book 9/8 of MONUMENTS at Page 35 at the request
 of LAWSON LAND SURVEYING