

**LH LAWSON**  
 LAND SURVEYING  
 LICENSED WASHINGTON AND OREGON  
 (206) 256-8008

JOHN G. LAWSON  
 Registered Professional Land Surveyor  
 Registered Professional Engineer

Y-Plaza  
 14612-A 4th Plain Rd  
 Vancouver, WA 98662

LAND CORNER RECORD

T 3 N, R 8 E, W.M.; Skamania county


Corner Code Number: L-19

Page 1 of 1

Name: Center One-quarter corner, Section 14 ; Corner Number L-19  
 DLC, HES Mining Claim, Indian Allotment, Federal Reserve, Townsite

1. History of Corner Establishment and Subsequent Restoration; description of Evidence Found:

This corner falls in the North wheel track of a dirt road. The brass cap is set 6" below ground level.



2. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record.

LAWSON LAND SURVEYING Job # 25 -82 - 150308 ; Date of Work: June, 1982

Set brass cap in 1-inch galvanized Iron Pipe 3 feet long and referenced as follows:

12-inch Fir, North 74° West, 23.8 feet (scribed)

16-inch Fir, South . ° West, 26.1 feet (scribed)

Washington Plane Coordinates: \_\_\_\_\_ Zone, Y \_\_\_\_\_, X \_\_\_\_\_

Order of Accuracy. Derived from: \_\_\_\_\_

Pin Pointed on Photo No. \_\_\_\_\_ Date \_\_\_\_\_ Located at \_\_\_\_\_

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973.

Signature John G. Lawson Date Oct 1982  
 Certificate Number 11989



AUDITOR'S CERTIFICATE

Filed for record this 3RD day of DEC, 1982 at 4:10 P.M.  
 In book 3/8 of MONUMENTS at Page 41 at the request  
 of LAWSON LAND SURVEYING