

LAND CORNER RECORD

T. 3 N, R. 8 East, W.M. Skamania County
Segregated Surveys: Corner Code No. C-9
Name: n/a Corner No.: n/a
DLC, RES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:
Originally set by G.L.O. surveyor, Robert A. Webster, in 1896.
No restoration found.

2. Description of Evidence Found:

24" Fir B.T. remains at S 60 E, 31.02 feet from corner position.
50" Cedar B.T. stump at S 36 W, 54.12 feet from corner position.
Stone mound and hub North 1 foot from corner position as determined from
found B.T. faces (not accepted).

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 600.22 Page No. 3 Date of work 11-3-82

On 11-3-82, the D.N.R. set a standard D.N.R. concrete monument with stamped brass cap by intersecting G.L.O. distances from B.T. stumps.

Shown on D.N.R. Final Map #462.

See corner diagram on reverse side.

Washington Plane Coordinates: South Zone, Y 163,842.43, X 1,664,755.25
3rd Order Accuracy. Derived From: 1975 Olson Eng. survey data at S.W.
corner Sec. 5 (Recorded in Bk 1 page 54, Records of Skamania County)
Pin Pointed on Photo No. Date. Located at.

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date Sept 29, 1983

Signature

11977 -
Certificate No.



AUDITOR'S CERTIFICATE

Filed for record this 6th day of OCTOBER 1983 at 1:10 P.M. In Book 3/8 of MONUMENTS at page 60 at the request of Washington State Department of Natural Resources

J.M. Olson by J. New, Dep.
County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.

12-1-82
~~11-3-82~~

LAIRD
GORDON
BRESSLER

$$\begin{array}{r} 3 \\ 1,00,22 \end{array}$$

SOUTH. 39.90 Bear CK. 501 S.W.

40.48 Set Post Marked $\frac{1}{4}$ S. on

24" fir	SLIKE	476	31.02
---------	-------	-----	-------

4/8" Cedar S37 1/2 W 82 L 54, 12

1/4 CORNER 544 T3N R8E

FOUND: B.T. PATTERN + MOUND OF
Rock w/ painted nub. I MEASURED FROM
FACES + PT Fell approx 1' SOUTH OF NUB, I DUG
TO FIND TRACE OF POST + FOUND NONE. MEAS.
FROM CENTERS + Fell 2' SOUTH OF MOUND (NUB)
AND G.L.D. BEARINGS FIT BETTER. SET MARKERS
FROM CENTER OF B.T.'S. Rocks of mound were
NOT mossy + ARE SUBJECT TO FLOODING IN
high water. OLD RUSTED ILLEGIBLE TAG, + Forest
SERVICE TAG SAYS "Approx 1/4 S 1/4" ON 18' older
6' N.W. of COR.

No other surveys of record.

12-1-82 After being to other corners around the section, I determined that the GLO surveyor measured from the faces of the RTs. I moved this monument to conform to that standard.

George

