

LAND CORNER RECORD

T 4 N, R 7E, W.M. SKAMANIA County Z-21
 Segregated Surveys: Corner Code No. N/A
 Name: N/A Corner No.: N/A
 D.C. RES. Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

D.L.C. HES. Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite

1. History of Corner Establishment and Subsequent Restoration: ORIGINALLY SET BY G.I.O. SURVEYOR, JACOB RICHARDSON, DURING 1895 G.I.O. SURVEY. IN 1903, G.I.O. SURVEYOR, ROBERT F. WHITHAM, SET THE CLOSING CORNER FOR 211, T3N-R7E, 3.14 CHAINS EAST OF THIS CORNER (HE DESTROYED MARKINS SOUTH OF LINE)



2. Description of Evidence Found:

2. Description of Evidence Found:
1 B.T. - REMAINS OF 36" FIR (WAXE MARKS) AT S75°E-34.3 FT.
OLD FOREST SERVICE TAGS
OLD UNREADABLE TAG UNDER THE SLUFFED OFF BARK
FROM THE S.E. B.T.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 600-24 Page No. 56 Date of work 10-13-83.

SHOWN ON D.N.R. F.M. # 477. SEE CORNER DIAGRAM
ON REVERSE SIDE.

SET STD. P.I.N.R. CONCRETE
MONUMENT W/STAMPED
BRASS CAP AT G.L.O.
BEARING & DIST. FROM
ROTTED 36" FIRE STUB.




Washington Plane Coordinates: SOUTH Zone, Y166205.30, X1642900.52
3RD Order Accuracy. Derived From: TIES TO USC & GS "GREENLEAF"
& USC & GS "SEDUM POINT"
 Pin Pointed on Photo No. _____ Date _____ Located at _____

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date December 1, 1983

Signature M. G. Kinnear 11977
Certificate No.



AUDITOR'S CERTIFICATE

Filed for record this 5 day of Dec 1983 at 11:40 P. M. In
Book 417 of Monuments at page 29 at the request of

BOOK 11 of monuments at page 11 at the request of
Dept of Natural Resources
Larry M. Olson
County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.

GLO Survey of 1895 (Jacob Richardson)
 80.00 - set post
 10" Fir N75E 52 lks 34.32'
 36" Fir S75E 52 lks 34.32'
 8" Fir S88W 75 lks 49.50'
 8" Fir N15W 54 lks 35.64'


In 1903, Robert Whitham, surveying
 T3N R7E, set a closing corner 3.14 ch east of
 this corner and destroyed markings south of line
 STD Sec. CORNER 35 36 T4N R7E

FOUND REMAINS OF 36" FIR
 S75E 34.3 FT. AXE MARK.
 OLD FOREST SERVICE TAGS
 ON BLAZED FIRS, 22" FIR S77E
 32' + 24" FIR N75E 33.7 FT. (TAG DOWN)

Found very old un readable tag under
 the sluffed off bark from the SE ST.

18296

10-13-83 LAIRD GORDON CRESSLER 56 600.24



SET CONC. MON. W/DNR BRASS CAP
 4" ABOVE GROUND AT G.L.O. BEARING +
 DIST. FROM ROTTED 36" FIR STUB

1.30
 12.70
 2.74