

OLSON ENGINEERING

1111 BROADWAY, VANCOUVER, WASH.
PH. (206) - 695-1385

1 KANAKA CR. RD., STEVENSON, WASH.
PH. (509) - 427-8411

BOOK 1/5 PAGE 21

LAND CORNER RECORD

96815

T 1 N, R 5E, W.M.
Segregated Surveys:

Skamania & Clark

County

Corner Code No. A-1

Name: Township Corner of T1N & 2N, R4E & 5E, WM

Corner No.

DLC, HES MINING CLAIM, INDIAN ALLOTMENT, FEDERAL RESERVE, TOWNSITE

1. History of Corner Establishment and Subsequent Restoration; description of Evidence Found:

Found 3 original bearing trees, all green.

Fir 55" diameter, bears North 78° West, 85.8 feet. (has been chopped out before)


Fir 48" diameter, bears South 50° East, 98.3 feet.

Fir 48" Diameter, bears South 64° West, 269.3 feet.

A 1 1/2" IP Bears South 85° West, 22 feet. A 1.6" fir reference bears South 23° East, 20.5 feet from the IP. This tree was scribed in about 1934, by Mr. Postal. According to Mr. Agun, who owns the property to the Southwest of this corner, Postal never found the original corner and set a marked post in the calculated position.

This area has not burned since 1855 and has not been logged, so the trees are in mint condition. I placed yellow bearing tree tags on the 3 bearing trees.

2. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. Page No. Date of work



Washington Plane Coordinates: Zone, Y, X

Order Accuracy. Derived From

Pin Pointed on Photo No. Date Located at

96815

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1972. Date 21 Feb 80

Signature

John G. Lawson

11989

Certificate No.

AUDITOR'S CERTIFICATE

Filed for record this 9th day of December 1983 at 11:50 A.M. of 1/5 of Monuments at Page 21 at the request of Olson Engineering



Mary M. Olson by B. Belbeck
County Auditor Deputy