



# OLSON ENGINEERING

1111 BROADWAY, VANCOUVER, WASH.

PH. (206) - 895-1385

1 KANAKA CR. RD., STEVENSON, WASH.

PH. (509) - 427-8411

BOOK 1/5 PAGE 24

## LAND CORNER RECORD

96318

T 1 N, R 5E, W.M.  
Segregated Surveys:

Skamania

County

Corner Code No. E-17

Name: Corner common to Sections 2,3,10 & 11

Corner No.

DLC, HES MINING CLAIM, INDIAN ALLOTMENT, FEDERAL RESERVE, TOWNSITE

### 1. History of Corner Establishment and Subsequent Restoration; description of Evidence Found:

Found a Skamania County Brass Cap in East-West fence line. A 48" diameter fir stub bears North 18° West, 134 feet. A 30" fir stump bears South 41° West, 134 feet. The two distances do not exactly match the GLO record and it looks like someone averaged the error between the two stumps. The 48 inch diameter tree is gone unless he miscalled the bearing to a 70" diameter fir snag.

*Handwritten signature/initials*

### 2. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. Page No. Date of work



Washington Plane Coordinates: Zone, Y, X

Order Accuracy. Derived From

Pin Pointed on Photo No. Date Located at

### 96318 SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date 26 Feb 84

Signature *John G. Lawson* Certificate No. 11989



### AUDITOR'S CERTIFICATE

Filed for record this 9th day of Dec. 1983 at 11:50 A.M.

1/5 of Monument at Page 24 at the request of Olson Engineering

*Handwritten signature: Gary M. Olson by B. Babcock*  
County Auditor