



OLSON ENGINEERING

1111 BROADWAY, VANCOUVER, WASH.
PH. (206) - 695-1385

1 KANAKA CR. RD., STEVENSON, WASH.
PH. (509) - 427-8411

BOOK 3/8 PAGE 70 LAND CORNER RECORD

96820

T 3 N, R 8E, W.M.
Segregated Surveys:

Skamania

County

Corner Code No. N-19

Name: N $\frac{1}{4}$ cor. Sec 23, T3N-R8E


Corner No.

DLC, HES MINING CLAIM, INDIAN ALLOTMENT, FEDERAL RESERVE, TOWNSITE

1. History of Corner Establishment and Subsequent Restoration; description of Evidence Found:

In Feb., 1910, C. E. linn County Surveyor, traverses from the NW cor. of Sec. 23 to the N $\frac{1}{4}$ cor. of Sec. 23. He notes finding the corner, but does not describe what he found. Also, there is a survey for Mr. Larson about this same time, tying a road into this one quarter corner. Louie Larson, one of the descendants who lives on the property Northeast of this corner, stated in 1968 that the old fence corner had been there as long as he could remember. A forester named Andrew Holman, in August 1938, found a North-South and East fence corner, which he accepted as the corner when he was surveying the Blue Ox Logging Rd. There are no remains of any bearing trees.

h
h
h



2. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. Page No. Date of work

We found a $\frac{1}{2}$ " IP and the remains of an old fence corner. From the past history and usage of this corner, we feel it is the best evidence of the original corner. In 1968, the Washington Department of Natural Resources had calculated this corner by proportionate measurement. Over this $\frac{1}{2}$ " IP, we set a $\frac{3}{4}$ " IP with a brass cap.

R. P.'s: 12" Douglas Fir with RR spike, 3 blazes and metal tag, N66°W, 15.64 ft.
16" Douglas Fir with RR Spike, 3 blazes and metal tag, S40°E, 3.34 ft.
14" Douglas Fir with RR Spike, 3 Blazes and metal tag, S45°W, 9.38ft.

Washington Plane Coordinates: Zone, Y, X

Order Accuracy. Derived From

Pin Pointed on Photo No. Date Located at


96820

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date 28 JAN 80

John G. Lawson
Signature

11989
Certificate No.



AUDITOR'S CERTIFICATE

Filed for record this 9th day of Dec 1983 at 11:50 A.M.
3/8 of Monuments at Page 70 at the request of Olson Engineering

Harry M. Olney by B. Baker
County Auditor