

State of Washington
DEPARTMENT OF NATURAL RESOURCES
BUREAU OF SURVEYS AND MAPS
LAND CORNER RECORD

Skamania County

T 3 N, R 6 E, W.M.

Corner Code No. A-15

Segregated Surveys:

Name: N/A

Corner Number: N/A

1. History of Corner Establishment and Subsequent Restoration: Originally set by G.L.O. Surveyor, Robert F. Whitham, during 1903 survey.

2. Description of Evidence Found:

- 1 60" fir snag with visible scribing at N18°W - 33.0 feet.
1 24" rotted hemlock stump at S18°E - 42.0 feet.



3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 600.23, Page No. 55. Date of work 8-4-83.

Shown on D.N.R. F.M. #489

See corner diagram on reverse side.

Set std. D.N.R. iron pipe
with stamped brass cap
from 2 found B.T.'s.

Washington Plane Coordinates: South Zone, Y 166,369.70, X 1,603,520.89
Third Order Accuracy. Derived from ties to "Swanberg Photo Control" Tgt's 100 & 101.
Pin Pointed on Photo No. _____, Date _____, Located at _____.


SURVEYOR'S CERTIFICATE

[Seal]

This corner record correctly represents work
performed by me or under my direction in compliance
with the provisions of Chapter 50, Laws of 1973.
Date 2-6-84.

H. Thomas Laird Jr.
Signature

21490
Certificate No.



AUDITOR'S CERTIFICATE

Filed for record this 9TH day of FEBRUARY 1984 at 1:15 P.M.
In Book 3/6 of MONUMENTS at page 22 at the request
of Washington State Department of Natural Resources.

X

M. M. Olson by A. New, Rep
County Auditor

620 OF 1903
 40.00 Set Post
 24" Hemlock S18 E 65L
 60" Fir N18 W 50 L.

1/4 CORNER $\frac{34}{3}$ TAN TSN R6E

FOUND: 60" Fir snag with scribing
 24" rotted hemlock stump

8-4-83

LAIRD
 GORDON
 DRESSLER
 WETHERTON
 GODDARD

WILLIS
 SCHAFFER 55
 600.23

