

State of Washington
DEPARTMENT OF NATURAL RESOURCES
BUREAU OF SURVEYS AND MAPS
LAND CORNER RECORD

Skamania County

T 4 N, R 6 E, W.M.

Corner Code No. Z-15

Segregated Surveys:

Name: N/A

Corner Number: N/A

1. History of Corner Establishment and Subsequent Restoration: Originally set by G.L.O. Surveyor, Robert F. Whitham, during 1903 survey.

2. Description of Evidence Found:

- 1 60" fir snag with visible scribing at N18°W - 33.0 feet.
1 24" rotted hemlock stump at S18°E - 42.0 feet.



3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 600.23, Page No. 55. Date of work 8-4-83.

Shown on D.N.R. F.M. #489

See corner diagram on reverse side.

Set std. D.N.R. iron pipe
with stamped brass cap
from 2 found B.T.'s.


Washington Plane Coordinates: South Zone, Y 166,369.70, X 1,603,520.89
Third Order Accuracy. Derived from ties to "Swanberg Photo Control" Tgt's 100 & 101.
Pin Pointed on Photo No. _____, Date _____, Located at _____.

SURVEYOR'S CERTIFICATE

This corner record correctly represents work
performed by me or under my direction in compliance
with the provisions of Chapter 50, Laws of 1973.
Date 2-6-84.

H. Thomas Laird Jr.
Signature

21490
Certificate No.



AUDITOR'S CERTIFICATE

Filed for record this 9TH day of FEBRUARY 1984 at 1:15 P.M.
In Book 4/6 of MONUMENTS at page 1 at the request
of Washington State Department of Natural Resources.

J.M. Olson by J. News, Dep.
County Auditor

620 OF 1903
 40.00 Set Post
 24" Hemlock S18 E 65L
 60" Fir N18 W 50 L

1/4 CORNER $\frac{34}{3}$ T4N R6E
 $\frac{3}{3}$ T3N


FOUND: 60" Fir snag with scribing
 24" rotted hemlock stump

8-4-83

LAIRD
 GORDON
 BRESSLER
 WETHERTON
 GOODMAN

WILLIS
 SCHAFER 55
 600.23

T4N
 R6E
 $\frac{34}{3}$
 S3
 T3N
 1983



SET DNR PIPE & CAP on steep SW slope.
 Cap 4" above ground, placed stones around
 pipe