

State of Washington
DEPARTMENT OF NATURAL RESOURCES
BUREAU OF SURVEYS AND MAPS
LAND CORNER RECORD

Skamania County

T 3 N, R 6 E, W.M.

Segregated Surveys:

Name: N/A

Corner Code No. C-21

Corner Number: N/A

1. History of Corner Establishment and Subsequent Restoration: Originally set by G.L.O. Surveyor, Robert F. Whitham, during 1903 survey.

2. Description of Evidence Found:

None.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 600.23A, Page No. 9. Date of work 9-27-82.

Shown on D.N.R. F.M. #489

See corner diagram on reverse side.

Set std. D.N.R. iron pipe
with stamped brass cap at
single-proportioned position.

Washington Plane Coordinates: South Zone, Y 164,511.22, X 1,611,372.48
Third Order Accuracy. Derived from ties to "Swanberg Photo Control" Tgt's 100 & 101.
Pin Pointed on Photo No. _____, Date _____, Located at _____.


SURVEYOR'S CERTIFICATE

This corner record correctly represents work
performed by me or under my direction in compliance
with the provisions of Chapter 50, Laws of 1973.
Date 2-6-84.

H. Thomas Lande Jr.
Signature

21490
Certificate No.

[Seal]

**AUDITOR'S CERTIFICATE**

Filed for record this 9th day of FEBRUARY 19 84 at 1:15 P.M.
In Book 3/6 of MONUMENTS at page 30 at the request
of Washington State Department of Natural Resources.

X
2

J.M. Olson By J. L. Nees, Dep
County Auditor

GLO of 1903
 25.37 CHAINS SOUTH; Set Post 4"x4"x8"
 18" Dead LARCH S 32-30E 38L
 12" Dead LARCH N 36-45W 21L

1/4 CORNER S 2 1/2 S 1 T 3 N R 6 E

FOUND NO TRACE ORIG
 CORNER.

9-27-82

GORDON
 BRESSLER
 LAIRD

9
 60023A

