

State of Washington
DEPARTMENT OF NATURAL RESOURCES
BUREAU OF SURVEYS AND MAPS
LAND CORNER RECORD

Skamania County

T 3 N, R 6 E, W.M.

Corner Code No. A-17

Segregated Surveys:

Name: N/A

Corner Number: N/A

1. History of Corner Establishment and Subsequent Restoration: Originally set by G.L.O. Surveyor, Robert F. Whitham, during 1903 survey.

2. Description of Evidence Found:

None.



3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 600.23A, Page No. 15. Date of work 9-28-83.

Shown on D.N.R. F.M. #489

See corner diagram on reverse side.

Set std. D.N.R. iron pipe
with stamped brass cap at
single-proportioned position.


Washington Plane Coordinates: South Zone, Y 166,283.10, X 1,606,156.72
Third Order Accuracy. Derived from ties to "Swanberg Photo Control" Tgt's 100 & 101.
Pin Pointed on Photo No. _____, Date _____, Located at _____.

SURVEYOR'S CERTIFICATE

This corner record correctly represents work
performed by me or under my direction in compliance
with the provisions of Chapter 50, Laws of 1973.
Date 2-6-84.

H. Thomas Laird Jr.
Signature

21490
Certificate No.



AUDITOR'S CERTIFICATE

Filed for record this 9th day of FEBRUARY 1984 at 1:15 P.M.
In Book 3/6 of MONUMENTS at page 34 at the request
of Washington State Department of Natural Resources.

Wm. Olson by J. Davis, Dep
County Auditor

GLO. of 1903
 80.00 CH Set Post in mound of Rocks
 12" Dead Larch N65°45'E 41 IKS.
 16" Dead Larch S36E 48 IKS.
 12 Dead Larch S29W 33 IKS.
 14" Dead Larch N49W 64 IKS.
 Section Cor $\frac{34}{32}$ T4N
 T3N R6E

FOUND NO TRACE OF .16
 CORNER DURING DILLIGENT
 SEARCH

9-28-83

GORDON
 BLESSLER
 Photographic

15
 600.23A

