

LAND CORNER RECORD

Skamania

County

T. 4 N, R. 7E, W.M.

Corner Code NoP-13

Segregated Surveys:

Name: One-quarter corner

Corner No.:

DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

Corner originally set by Deputy Jacob Richardson during July & August 1895 under contract No. 457.

Set post

Marked 40" Fir N32E-39 lks..

30" Fir S60W-38 lks..

2. Description of Evidence Found:

3/4" Iron pipe set by Olson Engineering.

Orig. 40" now 48" sawed D-Fir stump N32E-39 lks.(to face) scribing visible.

Orig. 30" now rotted D-Fir mound S60W-38 lks..

Steel fence post West.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 1 Page No. 6 Date of work Nov. 1983

Set 2 1/2"x30" Aluminum pipe with a 2 1/2" Aluminum cap.-Buried pipe next to monument.

New BT's:

Stamped:

12" Hemlock N9W-31.8 ft. scribed 1/8" S22BT and with

T4N R7E

a 3/4" Brass disk stamped PLS 16337.

1/4

12" D-Fir S15E-43.2 ft. scribed 1/8" S21BT and with

S21 S22

a 3/4" Brass disk stamped PLS 16337.

1983

PLS 16337

Set guard post East with decal survey marker only.

Nailed 54-4 and BT signs to BT's and painted band and blazes red.

Washington Plane Coordinates: Zone, Y, X

Order Accuracy. Derived From:

Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date 2/6/84

Signature

Certificate No. 16337

97148

AUDITOR'S CERTIFICATE

Filed for record this 4th day of FEBRUARY 1984 at 12:35 P.M. In Book 4/7 of MONUMENTS at page 89 at the request of

BISHOP SURVEYING, INC.

J.M. Olson by J. Davis, Dep.

County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.

