

Skamania

County

Corner Code No. V-25

Segregated Surveys:

Name: Section Corner Corner No.: Section

DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

Corner originally established by
Deputy Jacob Richardson under contract No. 457 during July 1895
marked:

8" Fir S71W-34 lks..
18" Cedar N52-30W-81 lks..

2. Description of Evidence Found:

Olson 3/4" in talus rock slide.
Orig. 24" now 48" D-Fir S18W-16C lks. chopped out blaze.



3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No.

2 Page No. 18 Date of work April 1984

Set 2½" x 30" Aluminum pipe with a 2½" Aluminum cap in a mound of stone. Marked: T4N R7E S25 S36 R7½E

Chisled XBO on top of 3'x4'x2' boulder
N69W-14.3 ft. to X.

Set guard post with decal "survey marker" only.
Nailed 54-4 and BT signs to BT's and painted band and blazes red.

Washington Plane Coordinates: Zone, Y, X

Order Accuracy. Derived From:

Pin Pointed on Photo No. _____ Date _____ Located at _____

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date April 19, 1984

Signature Larry D. Bishop

16337
Certificate No.



AUDITOR'S CERTIFICATE

Filed for record this 23RD day of MAY 1984 at 1:55 P.M. In
Book 47 of MONUMENTS at page 93 at the request of

LARRY D BISHOP

Wm. Olson by J. Davis, Dep.
County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.