

LAND CORNER RECORD

T 4N N, R. 7E, W.M. Skamania County
Segregated Surveys: Corner Code No. X-21
Name: One-Quarter corner Corner No.: $\frac{1}{4}$
DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

This corner was not set during the original survey.

2. Description of Evidence Found:

None

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 3 Page No. 10 Date of work April 1984

Set $2\frac{1}{2}$ " x 30" Aluminum pipe with a $2\frac{1}{2}$ " Aluminum cap. Marked: T4N
New Bearing Trees: $\frac{1}{4}$
14" D-Fir N86E-14.2 ft. scribed $\frac{1}{8}$ S36BT and with R7E | S36
a $\frac{3}{4}$ " Brass disk stamped PLS 16337. R7E
16" D-Fir S32E-46.5 ft. scribed $\frac{1}{8}$ S36BT and with 1984
a $\frac{3}{4}$ " Brass disk stamped PLS 16337. PLS 16337

Set guard posts North and South with 54-2 and land survey decals.

Nailed 54-4 and 54-3 signs to BT's and painted band and blazes red.

Washington Plane Coordinates: _____ Zone, Y _____, X _____
Order Accuracy. Derived From: _____

Pin Pointed on Photo No. _____ Date _____ Located at _____

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date April 19, 1984

Larry D. Bishop 16337
Signature Certificate No.



AUDITOR'S CERTIFICATE

Filed for record this 23RD day of MAY 1984 at 2:25 P.M. In
Book $\frac{1}{2}$ of MONUMENTS at page 27 at the request of

LARRY D. BISHOP

L.M. Olson by L. New, Dep.
County Auditor