LAND CORNER RECORD

	County Corner Code No. J=14.5
4 N, R 9E , W.M. gregated Surveys:	Corner Code No.
me: One-sixtyfourth DLC, HES, Tract, Mining C	Corner No.:
History of Corner Establishment and Subsequent Restoration:	
N/A	iosequent restoration.
Description of Evidence Found:	
Iron rod N10-22-20E-23.49 leet.	15:24 - 15:24
	W11681997
Describe Monument, Accessories and Congram corner and indicate meridian and3_ Page No13 Date of work	rollary Data to Perpetuate this Corner Location. Dis reference to map of record. Surveyor's Field Book No. July 1984
Set 2½" x 30" Aluminum pipe with 2½" New Bearing Trees: 8" D-Fir N51W-11.5 ft. scribed F with 3/4" Brass disk stamped PLS 8" D-Fir S87W-7.5 ft. scribed FW with 3/4" Brass disk stamped PLS Set guard posts South and East with Nailed 54-9 and BT signs to BT's and	\$10 EW1/64S 10BT and EW1/64— S 16337. \$15 W1,64S15BT and \$1984 S 16337. PLS 16337 both decals.
Order Accuracy. Derived 1	Zone, Y X
Pin Pointed on Photo No. Date	Located at
	ICATE [SEAL]
SURVEYOR'S CERTIFICATION This corner record correctly represents	work performed by me or
SURVEYOR'S CERTIFICATION This corner record correctly represents under my direction in compliance with 50 Laws of 1973. Date July 1986	work performed by me or the provisions of Chapter
SURVEYOR'S CERTIFICATION This corner record correctly represents under my direction in compliance with	work performed by me or the provisions of Chapter 16337 Certificate No.
This corner record correctly represents under my direction in compliance with 50, Laws of 1973. Date. July 1984 Signature AUDIT	work performed by me or the provisions of Chapter