

LAND CORNER RECORD

Skamania County
T 4 N, R 9E, W.M.
Segregated Surveys:
Name: One-quarter corner Corner No.:
DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

The corner was originally set by Deputy Jacob Richardson during Oct./Nov. 1892 under contract No. 383.

Set post:

Scribed 6" Fir N5W-26 lks..

10" Fir N37W-8 lks..

2. Description of Evidence Found:

1 1/2" Iron pipe with cap.

Orig. 10" now 26" D-Fir S37W-8 lks. (record N37W) chopped on repeatedly-probable scribed marks.

Orig. 6" now 20" D-Fir snag N5W-26 lks.-face chopped out and now rotted-scribing visible.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 3 Page No. 14 Date of work July 1984

Set 2 1/2" x 30" Aluminum pipe with 2 1/2" Aluminum cap. Marked:

New Bearing Trees:

20" D-Fir S89W-9.0 ft. scribed 1/8" S15BT and

with 3/4" Brass disk stamped PLS 16337.

10" D-Fir N61E-60.5 ft. scribed 1/8" S10BT and

with 3/4" Brass disk stamped PLS 16337.

Set guard posts East and West with both decals.

Nailed 54-4 and BT signs to BT's and painted band and blazes red.

Buried pipe in hole next to monument.

T4N R9E

S10

S15

1984

PLS 16337

Washington Plane Coordinates: Zone Y, X

Order Accuracy. Derived From:

Pin Pointed on Photo No. Date Located at.


SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date July 1984

Signature *Larry D. Bishop*

16337
Certificate No.

[SEAL]



AUDITOR'S CERTIFICATE

Filed for record this 24th day of JULY 1984 at 1:10 P.M. In Book 4/9 of MONUMENTS at page 65 at the request of

BISHOP SURVEYING, INC.

J. M. Olson by *J. M. Olson, Dep.*
County Auditor