

BUNTING & ASSOCIATES RS & SURVEYORS 1 326 Phose 206-494-4555 Packwood, Wa. 98361

LAND CORNER RECORD

W.M.

County

Segregated Surveys:

XEWIS Skamania

Name:

Corner Code No. J-13 Cor for Secs. 9, 10, 15 & 16

Corner No.:...

DLC. HES. Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

History of Corner Establishment and Subsequent Restoration: Set a granite stone, 24x16x8 ins., 18 ins. in the ground, for cor of secs. 15 & 16, marked with 4 notches on S. and 3 notches on E edge; from which Hemlock, 30 ins. dia., bears N. 67° E., 5 lks. dist., mkd. T 10 N R 6 E Hemlock, 36 ins. dia., bears S. 41° E., 33 lks. dist., mkd. T 10 N R 6 E Hemlock, 20 ins. dia., bears S. 71° W., 51 lks dist., mkd. T 10 N R 6 E Hemlock, 30 ins. dia., bears N 28½° W., 79 lks. dist., mkd. T 10 N R 6 E	S 10 B T. S 15 B T.
Description of Evidence Found: Stone approx. 8x16 ins., 6 ins. under Mt. St. Helens ash, with 4 notches i and 3 notches in E edge, from which Hemlock stump bears N28½°W, 51.76 ft. dist., mkd. "R 6 S" with other scr overgrown. Hemlock stump out of ground and leaning but stump hole located original within a few feet, bears approx. N67°E, approx. 3 ft. dist., no marking At a third bearing tree distance and bearing from the stone, a depression probably the stump hole of bearing tree long ago rotted away. At the fourth bearing tree distance and bearing, no evidence could be seconder's location had been wrified by Forest Service before recent logging.	ibing position gs remaining. n was found,

3. Describe Monument. Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. Page No...... Date of work

Left the stone undisturbed except uncovered and extending 3" above the ground, from which

An iron pipe, $2\frac{1}{2}$ " dia., 30" long, 24" in ground, with split and flared bottom end, bears S71°W, 35.03 ft. dist., mkd. REFERENCE MONUMENT S71W 35.03 FEET 11564. An iron pipe, $2\frac{1}{2}$ " dia., 30" long, 24" in ground, with split and flared bottom end, bears N28 $\frac{1}{2}$ °W, 47.66 ft. dist., mkd. REFERENCE MONUMENT N28 30W 47.66 FEET 11564. The stumps described above.

Note that bearings of two of the new pipe reference monuments are intentionally the same as bearings of two of the original bearing trees.

Bearing basis was magnetic needle with declination 22° east.

Washington Plane Coordinates:	Zone, Y		172-
Order Accuracy. Derived	d From:		Life .
Pin Pointed on Photo No Dat	eLoca	ited at.	The second

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date. June 29, 1984

1156L Certificate No.

98169

AUDITOR'S CERTIFICATE Filed for record this 10 1H day of SEPTEMBER 1984 at 12:20 of MONUMENTS at page 13 BUNTING & ASSOCIATES ... at the request of...

all Oben County Auditor

ONAL LAND

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2),