

## LAND CORNER RECORD

Skamania

County

T. 3 N. R. 7 E. W.M.

Corner Code No. J-23

Segregated Surveys:

Name:

N/A

Corner No.: N/A

DLC. HES. Tract. Mining Claim. Indian Allotment. Federal Reserve. Townsite.

## 1. History of Corner Establishment and Subsequent Restoration:

G.L.O. survey by Jacob Richardson in 1893. Set post and two B.T.'s Re-established by single proportion by Bert Mason in 1966. Found no evidence of original corner or bearing trees. Corner fell in old fir stump. He set iron rod 2' north of corner. D.N.R. set concrete monument witness corner in 1968.

## 2. Description of Evidence Found:


Found D.N.R. brass disc set in concrete.

12" fir with tag and healed over blaze, bears No. 52° W. 24.9 feet, (marked S. 40° E.)

12" white fir with D.N.R. tag and no blaze, bears N. 80° E. 21.2 feet.

18" fir with D.N.R. tage and healed over blaze, bears S. 50° E. 45 feet. Distances to center of trees.

## 3. Describe Monument. Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. \_\_\_\_\_ Page No. \_\_\_\_\_ Date of work May 18, 1984



Washington Plane Coordinates: \_\_\_\_\_ Zone, Y \_\_\_\_\_, X \_\_\_\_\_  
Order Accuracy. Derived From: \_\_\_\_\_

Pin Pointed on Photo No. \_\_\_\_\_ Date \_\_\_\_\_ Located at \_\_\_\_\_

## SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date July 31, 1984

Signature

11733  
Certificate No.

98032

## AUDITOR'S CERTIFICATE

Filed for record this 9th day of AUGUST 1984 at 3:00 P.M. In Book 3/7 of MONUMENTS at page 53 at the request of

TENNESON ENGINEERING CORP.

Simon by d. Davis, Dep  
County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.

