

98937

BOOK 3/5 PAGE 6

State of Washington
DEPARTMENT OF NATURAL RESOURCES
BUREAU OF SURVEYS AND MAPS
LAND CORNER RECORD

13

24

Skamania County

T 3 N, R 5 E, W.M.

Segregated Surveys:

Name: n/a


Corner Code No. N-25

Corner Number: n/a

1. History of Corner Establishment and Subsequent Restoration: Originally set by GLO in 1892.

2. Description of Evidence Found:

60" fir snag with old tags at S48W, 21.1 feet. (BT)
30" hemlock uproot at N85W, 69.3 feet. (BT)



3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 600.21, Page No. 55. Date of work 3-24-82.

See reverse side for sketch.

Washington Plane Coordinates: South Zone, Y 151,348.605, X 1,585,106.452 Third Order Accuracy.

Derived from: Ties to USC & GS "Lookout Mountain" and DNR 1, T3N, R6E.

Pin Pointed on Photo No. _____, Date _____, Located at _____.

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date February 20, 1985.

H. Thomas Laird Jr.
Signature

21490
Certificate No.

[Seal]



AUDITOR'S CERTIFICATE

Filed for record this 21st day of FEBRUARY 1985 at 12:55 P.M.
In Book 3/5 of MONUMENTS at page 62 at the request
of Washington State Department of Natural Resources.

S
S

William J. Davis, Dep.
County Auditor

CHO of 1882

60.00 Set post, from which ---

60" Fir S47-45W 32 L 21.12

30 Hemlock N86-30W 105 L 69.50

Section Corner $\frac{13}{24}$ T3N R5E

FOUND

60" FIR SNAG W/OLD TAGS

NO SCRIBE S48W 21.1 FT



30" HEM UPROOT NO SCRIBE

N85W 69.3 FT

3-24-82

ORDON
CAT 5511

SS
670.21



THE CORNER IS A 3" CYL CONC. MON
W/OLD BRASS CAP 3" ABOVE GROUND
CORNER LIES ON HILLSIDE SLOPING
STEADILY TO NORTH AND IS APPROX 130'
SOUTH OF FOOT OF THE SLOPE