Found:

LAND SURVEYING

(206) 256-8008

the East side of Wind River canyon.

Washington Plane Coordinates:

of TOHN LAWSON

Signature

Pin Pointed on Photo No.____ Date _

SURVEYOR'S CERTIFICATE

IOHN G LAWSON red Professional Engine 14612-A 4th Plain Rd. Vancouver, WA 98662

LAND CORNER RECORD T 4 N, R 7E , W.M.; Skamania county Corner Code Number:____ Page <u>1</u> of <u>1</u> Corner Name: Section corner, 25, 26, 35, 36
DEC, HES Mining Claim, Indian Allotment, F. deral Reserve, Townsite Number_ 1. History of Corner Establishment and Subsequent Restoration; description of Evidence This corner was established by U.S. Deputy Surveyor Jacob Richardson in July, 1895. It was found in May, 1916 by Frederick W. Rase during a survey he made in May, 1916. The corner had been destroyed by a rock slide, but the Fir, 30" in diameter, Section 36 B.T. was found scribed and in good condition in 1916. We found a \pm 28" diameter Fir snag without bark and gnarled fire scars. There was some fairly recent axe work on a scar \pm 4' above the ground. We sawed out scars, but found only pitch seams. No scribing or axe work was found. Original B.T. must have been bark scribed. G.L.O. bearing and distance from this snag places the corner within 2 feet of the location matching 1916 witness corner to the East. 2. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corper and indicate meridian and reference to map of record. Date of Work: November, 1983 LAWSON LAND SURVEYING Job # 34 -83 - 26046" This corner falls on side of a vertical rock cliff so we set a witness corner on JUN 1985 Order of Accuracy. Derived from: ____Located at This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. in Fard, Cir Date June 85 Certificate Number 11989 99393 AUDITOR'S CERTIFICATE Filed for record this 17th day of JUNE, 1985 at 2:35 of <u>MUNUMENTS</u> at Page <u>95</u> at the request

County Auditor