

RES 20-1808(4-77)

## LAND CORNER RECORD

SKAMANIA County  
T. 7 N, R. 5E, W.M. Corner Code No. Q-6  
Segregated Surveys:  
Name: Southwest 1/16 Corner Section 20 Corner No.: SW 1/16 S20  
DLC, RES, Tract, Mining, Claim, Indian Allotment, Federal Reserve, Townsite.


## 1. History of Corner Establishment and Subsequent Restoration:

NONE

## 2. Description of Evidence Found:

NONE

## 3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 259-C Page No. 19 Date of work 8-8-84



Set a 2 1/2" x 30" Aluminum Pipe, 26" in the ground with an aluminum cap. No stone available with 250' for stone mound. Cleared a 12' circle around monument.

Painted a 6" orange band around all BT's and painted faces.

Set a 6' fibreglass guard post N45°W 5.00 FT Attached USFS 54-3 and 54-9 signs on all BT's with 54-9 sign.

Nailed brass survey washers LS 20898 in the top circle of newly scribed "B"'s and also at point of measurement on side of trees.

No  
Scale

Washington Plane Coordinates: Zone, Y. Order Accuracy. Derived From:


Pin Pointed on Photo No. Date Located at

## SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date August 10, 1984

Signature

Certificate No. 20898



## AUDITOR'S CERTIFICATE

Filed for record this 23RD day of AUGUST 1985 at 11:35AM. In Book 7/5 of MONUMENTS at page 68 at the request of

BUTLER & ZENKNER LAND SURVEYORS, INC.

Jim Olson by d. New, Dep.

County Auditor

Registered  
Indexed  
Indirect  
Filed  
Mailed

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.