

LAND CORNER RECORD

36
T 6

SKAMANIA

County

Corner Code No. A-1

T 4 N. R. S E. W.M.
Segregated Surveys:

Name:

Corner No.:


DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration: GLO OCT 20, 1897 CHARLES A. HONAN US DEPUTY SURVEYOR. FOUND BY USFS APPROX 1939. THEY SET 3'x3" CEDAR POST AND 3/4" I.P. HE FOUND REMAINS OF 1897 BT'S. RESET 2 1/2" ALUMINUM PIPE WITH CAP AT POST POSITION.

2. Description of Evidence Found: 3'x3" CEDAR POST; 3/4" IRON PIPE
REMAINS 30" HEMLOCK SB2W 22.4 NO MARKS
GLO 30" HEMLOCK SB2W 34 2KS.
REMAINS 36" FIR SNAG 559E 35.6 POSSIBLE AXE MARKS
GLO 36" F 559E 54 RKS

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 1-85 Page No. 6 Date of work 7-26-83

☐ REFERENCE PLATE
☒ SA-4 SIGN ON BACK
☒ 1/4x2 1/4" GALVANIZED NAIL ON CENTER SIDE OF TREE
CARBONITE POST 2' SOUTH



14" FIR
☒ ☐ ☒
MARKED
CC TAN R4E S1 BT

6" FIR
☒ ☐ ☒
MARKED
CC TAN R5E S6 BT

MAGNETIC

Washington Plane Coordinates: Zone, Y
Order Accuracy. Derived From:

Pin Pointed on Photo No. Date Located at.

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date 8-2-83

Signature

LS 16 196
Certificate No.



AUDITOR'S CERTIFICATE

Filed for record this 11th day of SEPTEMBER 1985 at 2:20 P. M. In Book 4/5 of MONUMENTS at page 12 at the request of

ARCHIE B. CARPENTER

James B. Davis
County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.