SURVEY IN PART W/2 SECTION 36, TWP. 3 N., RGE. 7 E., W.M. IN PART LOTS 1 \$2, ELECTRIC ADD'N TO STEVENSON

BASIS OF BEARINGS: E-W centerline of Section 36 taken as \$89°23'25"W


LEGEND:

- Found corner monument or as noted.
- Set 5/8"x30" iron rod with plastic cap

- 1. Found iron pipe, no record of establishment. Line established by this survey indicates a garage encroachment onto TL 600 of approximately one foot. Found iron pipe bears N44°07'41"E 7.96 from set witness corner.
- 2. Corners found for boundary of Rutledge Addition indicate an encroachment of approximately nine feet West onto Lot 2 of the Electric Addition. This corner destroyed during construction.
- 3. Found iron pipe bears N14°23'29"E, 12.52 feet from new corner set. Found corner considered not acceptable.
- 4. Corners found considered unacceptable for lot corners, but southwest corner used for north-south alignment only.
- 5. Found iron pipe set by Olson Engineering in 1978 for true center of section, but not used for this survey. Earlier found center used for this survey.

LOT 10 of Rutledge Addition not marked in this survey.

See Report of Survey, filed with the Skamania County Engineer, for details regarding this survey.



AUDITOR'S CERTIFICATE

Filed for record this _____day of AddUST,1985 at _____en in Book ____ of Surveys at Page _____ at the request of Trantow Surveying.

SURVEYOR'S CERTIFICATE

This map correctly represents a survey made by me or under my direction in conformance with the requirements of the Survey Recording Act at the request of NORWOOD, INC. in JUNE, 1985



Very Weantow LS 15673



T. N. TRANTOW SURVEYING, P. L. S. P. O. Box 287, Bingen, Washington 98605 (509) 493-3111

SURVEY FOR

NORWOOD, INC.

SKAMANIA CO., WASH.

Surveyed by **D.P.** - **R.J.** Date **7-85** Scale ("=/00')

Drawn by **7.7.** Date **8-85** Sheet / of / Checked by Date 8-7-85 Project No. 85228

