

LAND CORNER RECORD

(THIS FORM PRESCRIBED BY THE PUBLIC LAND SURVEY OFFICE, DEPARTMENT OF NATURAL RESOURCES, PURSUANT TO RCW 58.09. ALPHA-NUMERIC INDEX DIAGRAM ON THE BACK.)

116159

Corner Indexing Information:

TWP 2 North RGE 6 East Corner Code V-11
(Willamette Meridian)

ADDITIONAL IDENTIFIER: (e.g., BLM designation for the corner, street intersection, plat name, block, lot, etc.)

North quarter of Section 33, Township 2 North, Range 6 East, Willamette Meridian.

Skamania County Washington:

AUDITOR'S USE

Land Surveyor Information: (or Public Officer as per RCW 58.09.090)

This corner record correctly represents work performed by me or under by direction in conformance with the Survey Recording Act.

Company or agency:
Minister & Glaeser Surveying, Inc.
2208 E. Evergreen Blvd.
Vancouver, WA. 98661
Phone: (206) 694-3313
Fax: (206) 694-8410



Signature Robert W. Glaeser Date: 4-20-93 Seal: 15024
Washington Plane Coordinates: N: _____ E: _____
Order: _____ Zone: _____ Datum (Date of adjustment): _____

Corner Information: Use the space below to provide the following information regarding the corner.

(1) Pertinent Corner History:

The original survey was conducted by Deputy Surveyor Charles E. Sears, under Contract No. 287, dated December 23, 1882. The survey was performed between March 16, and June 26, 1883. Set a post 3 feet long, 3 inches square, and 18 inches in a mound of stones, 39.92 chains West from the Northeast corner of Section 33.

B.T.'s were as follows:

60" Diam. Dead Fir, North 16° West, 45 Links
40" Diam. Dead Fir, South 40° East, 63 Links


(2) Evidence Found at the Corner:

No original evidence was found.

Found Skamania County brass cap set in concrete, which was accepted as the corner based on reputation and use.

(3) Corner Perpetuation Information:

<u>Surveys</u>		<u>Short Plats</u>
Book 1, Page 206	Book 2, Page 144	
Book 1, Page 97	Book 1, Page 256	




MARK THE CORNER LOCATION ON THE DIAGONAL BEACH AND FILL IN THE CORNER CODE BLANKS ON THE OTHER SIDE.

BOOK 135 PAGE 69

	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
A																									
B																									
C			6				5					4				3				2					
D																									
E																									
F																									
G			7				8					9				10				11					
H																									
J																									
K																									
L			18				17					16				15				14					
M																									
N																									
O																									
P			19				20					21				22				23					
Q																									
R																									
S																									
T			30				29					28				27				26					
U																									
V																									
W																									
X			31				32					33				34				35					
Y																									
Z																									

RCW 58.09.060 (2) requires the following information on this form: an accurate description and location, in reference to the corner position, of all monuments and accessories (a) found at the corner and (b) placed or replaced at the corner; (c) basis of bearings used to describe or locate such monuments or accessories; and (d) corollary information that may be helpful to relocate or identify the corner position.

SPACE FOR ADDITIONAL COMMENTS:



3" BRASS CAP
"STAMPED"

FND. 1.4 ABOVE GROUND



NOTE:

PLACED ALUM. NAIL WITH
PLASTIC TAG, MARKED
GLAESER #15024,
AT ALL R.P.'S

