FUED FOR RECORD SKARANIA CO WASH 11 Robert Glasser

LAND CORNER RECORD

HAY 4 2 44 PM 193 GARY M. OLSON

(THIS FORM PRESCRIBED BY THE PUBLIC LAND SURVEY OFFICE, DEPARTMENT OF NATURAL RESOURCES, PURSUANT TO RCW 58.09. ALPHA-NUMERIC INDEX DIAGRAM ON THE BACK.)

BOOK 135 PAGE 77

116161 Corner Indexing Information:

TWP 2 North RGE <u>6 East</u> (Willamette Meridian)

__Corner Code<u>Z-11</u>

ADDITIONAL IDENTIFIER: (e.g., BLM designation for the corner, street intersection, plat name, block, lot, etc.)

South quarter of Section 33, Township 2 North, Range 6 East, Willamette Meridian.

<u> Skamania County Washington:</u>

AUDITOR'S USE

Land Surveyor Information: (or habite Officer as per RCW 58.09.099)

This corner record correctly represents work performed by me or under by direction in conformance with the Survey Recording Act.

Company or agency: Minister & Glaeser Surveying, Inc. 2208 E. Evergreen Blvd. Vancouver, WA. 98661 Phone: (206) 694-3313 Fax: (206) 694-8410

EXPIRES

Date: 4 - 20-93

Washingtor Plane Coordinates: N:

Zone:

Datum (Date of adjustment):

Corner Information: Use the space below to provide the following information regarding the corner.

(1) Pertinent Corner History:

The original survey was conducted by Deputy Surveyors Lewis VanVleet and John Newsom, under Contract No. 7, dated April 23, 1859. The survey was performed between April 29, and 30, 1859. Set a post 40.00 chains East from the Southwest corner of Section

B.T's were as follows:

12" Diam. Maple, North 45° East, 14 Links

30" Diam. Fir, South 45° West, 39 Links A resurvey was conducted by Deputy Surveyor Charles E. Sears, under The survey was Contract No. 287, dated December 23, 1882. performed between March 16 and June 26, 1883. They found remains of the quarter corner post in the ground and the bearing trees were standing. Therefore a new post, 3 feet long and 3 inches square was set 24 inches into the ground, 40 chains East from the Southwest corner of Section 33.

B.T.'s were as follows:

12" Diam. Maple, North 45° 14 Links

30" Diam. Fir, South 45 West, 39 Links

(2) Evidence Found at the Corner: No original evidence was found. Skamania County brass cap was accepted as the corner based on reputation and use.


Corner Perpetuation Information: Surveys

Short Plats

Book 2, Page 144

Book 1, Page 97

Book 2, Page 237



RCW 58.09.060 (2) requires the following information on this forms an accurate description and location, in reference to the corner position, of all monuments and accessories (a) found at the corner and (b) placed or replaced at the corner; (c) basis of bearings used to describe or locate such monuments or accessories; and (d) corollary information that may be helpful to relocate or identify the corner position.

SPACE FOR ADDITIONAL COMMENTS

