

FILED IN RECORD
SKAMANIA CO. WASH
By Robert Glaeser

MAY 4 2 48 PM '93

P. Lowry

GARY H. OLSEN

LAND CORNER RECORD

(THIS FORM PRESCRIBED BY THE PUBLIC LAND SURVEY
OFFICE, DEPARTMENT OF NATURAL RESOURCES, PURSUANT
TO RCW 58.09. ALPHA-NUMERIC INDEX DIAGRAM ON
THE BACK.)

BOOK 135 PAGE 79

116162

Corner Indexing Information:

TWP 2 North RGE 6 East Corner Code Z-13
(Willamette Meridian)

ADDITIONAL IDENTIFIER: (e.g., BLM designation
for the corner, street intersection, plat name,
block, lot, etc.)

Southeast corner of Section 33, Township 2 North, Range 6
East, Willamette Meridian.


Skamania County Washington:

AUDITOR'S USE

Land Surveyor Information: (or Public Officer as per RCW 58.09.090)

This corner record correctly represents work performed by me or
under by direction in conformance with the Survey Recording Act.

Company or agency:
Minister & Glaeser Surveying, Inc.
2208 E. Evergreen Blvd.
Vancouver, WA. 98661
Phone: (206) 694-3313
Fax: (206) 694-8410



Signature [Signature] Date: 4-20-93 Seal: 15024
Washington Plane Coordinates: N: E:
Order: Zone: Datum (Date of adjustment):

Corner Information: Use the space below to provide the following
information regarding the corner.

(1) Pertinent Corner History:

The original survey was conducted by Deputy Surveyor Lewis VanVleet
and John Newsom, under Contract No. 7, dated April 23, 1859. The
survey was conducted between April 29, and 30, 1859. Set a post
for corner common to Sections 3, 4, 33 and 34, 80 chains East from
the Southwest corner of Section 33.

B.T.'s as follows:

- 15" Diam. Oak, North 69° East, 127 Links
- 15" Diam. Oak, South 78° East, 67 Links
- 20" Diam. Oak, South 49° West, 141 Links
- 60" Diam. Fir, North 17° West, 200 Links

(2) Evidence Found at the Corner:

No original evidence was found.

Found 3/4 inch Iron Pipe, which was accepted as the corner based on
reputation and use.

(3) Corner Perpetuation Information:

Surveys		Short Plats
Book 2, Page 144	Book 1, Page 34	Book 2, Page 41
Book 1, Page 97		

Ordered p
Indexed, Dir p
Filed p
Mailed p

MARK THE CORNER LOCATION ON THE DIAGRAM BELOW AND FILL IN THE CORNER CODE BLANK ON THE OTHER SIDE.

BOOK 135 PAGE 80

	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
A																									
B																									
C			6				5			4				3				2						1	
D																									
E																									
F																									
G			7				8			9				10				11						12	
H																									
J																									
K																									
L			18				17			16				15				14						13	
M																									
N																									
O																									
P			19				20			21				22				23						24	
Q																									
R																									
S																									
T			30				29			28				27				26						25	
U																									
V																									
W																									
X			31				32			33				34				35						36	
Y																									
Z																									

RCW 58.09.060 (2) requires the following information on this form: an accurate description and location, in reference to the corner position, of all monuments and accessories (a) found at the corner and (b) placed or replaced at the corner; (c) basis of bearings used to describe or locate such monuments or accessories; and (d) corollary information that may be helpful to relocate or identify the corner position.

SPACE FOR ADDITIONAL COMMENT:

NOTE: PLACED ALUM. NAIL WITH PLASTIC TAG, MARKED GLAESER #15024, AT ALL RP'S

