

FILED FOR RECORD
SKAMANIA CO. WASH
BY *Robert Glaeser*

MAY 4 2 51 PM '93

P. Lawry

GARY M. OLSON

LAND CORNER RECORD

(THIS FORM PRESCRIBED BY THE PUBLIC LAND SURVEY
OFFICE, DEPARTMENT OF NATURAL RESOURCES, PURSUANT
TO RCW 58.09. ALPHA-NUMERIC INDEX DIAGRAM ON
THE BACK.)

116163

BOOK 135 PAGE 81

Corner Indexing Information:

TWP 1 North RGE 6 East Corner Code A-9
(Willamette Meridian)

ADDITIONAL IDENTIFIER: (e.g., BLM designation
for the corner, street intersection, plat name,
block, lot, etc.)

Northeast corner of Section 5, Township 1 North, Range 6 East,
Willamette Meridian.

Skamania County Washington:


AUDITOR'S USE

Land Surveyor Information: (or Public Officer as per RCW 58.09.090)

This corner record correctly represents work performed by me or
under by direction in conformance with the Survey Recording Act.

Company or agency:

Minister & Glaeser Surveying, Inc.
2208 E. Evergreen Blvd.
Vancouver, WA. 98661
Phone: (206) 694-3313
Fax: (206) 694-8410



Signature *Robert W. Glaeser*

Date: 4-20-93

Seal: 15024

Washington Plane Coordinates: N:
Order:

Zone:

E:
Datum (Date of adjustment):

Corner Information: Use the space below to provide the following
information regarding the corner.

(1) Pertinent Corner History:

The original survey was conducted by Deputy Surveyors Lewis
VanVleet and John Newsom under Contract No. 7, dated April 29,
1859. Set a post for corner common to Sections 4, 5, 32 and 33,
80 chains East from the Northwest corner of Section 5.

B.T.'s as follows:

- 10" Diam. Chittum, North 65° West, 3 Links
- 15" Diam. Chittum, South 75° East, 18 Links
- 7" Diam. Dogwood, South 22° West, 51 Links
- 18" Diam. Maple, North 40° East, 54 Links

A resurvey was conducted by Deputy Surveyor Charles E. Sears
under Contract No. 287, Dated December 23, 1882. The survey was
conducted between March 16 and June 26, 1883.

A evidence of corner to Sections 4, 5, 32, and 33 was destroyed
by the clearing of land. Corner was re-established 80.00 chains
East of the Southwest corner of Section 32. Set a post 4 feet
long and 4 inches square, 24 inches into ground.

B.T.'s as follows:

Registered ☒
Indexed, Dir ☒
Indirect ☒
Filed ☒
Marked ☒

36" Diam. Fir, North $46^{\circ}-30'$ East, 128 Links
 30" Diam. Fir, South 63° East, 170 Links

BOOK 135 PAGE 82

(2) Evidence Found at the Corner:

No original evidence was found.

Axle shaft was accepted as the corner based on reputation and use.

(3) Corner Perpetuation Information:


Surveys

Book 2, Page 237
 Book 2, Page 9

Short Plats

Book 1, Page 97

MARK THE CORNER LOCATION ON THE DIAGRAM BELOW AND FILL IN THE CORNER CODE BLANK ON THE OTHER SIDE:



ACH 58.09.060 (2) requires the following information on this form: an accurate description and location, in reference to the corner position, of all monuments and accessories (a) found at the corner and (b) placed or replaced at the corner; (c) basis of bearings used to describe or locate such monuments or accessories; and (d) corollary information that may be helpful to relocate or identify the corner position.

SPACE FOR ADDITIONAL COMMENTS:

