

LAND CORNER RECORD

(THIS FORM PRESCRIBED BY THE PUBLIC LAND SURVEY OFFICE, DEPARTMENT OF NATURAL RESOURCES, PURSUANT TO RCW 58.09. ALPHA-NUMERIC INDEX DIAGRAM ON THE BACK.)

FILED FOR RECORD
SKAMANIA CO. WASH
BY *Bob Glaeser*

FEB 14 39 PM '94
P. Lawry
AUDITOR
GARY M. OLSON

Corner Indexing Information:

TWP 1 N RGE 5 E Corner Code E-9
(Willamette Meridian)

ADDITIONAL IDENTIFIER: (e.g., BLM designation for the corner, street intersection, plat name, block, lot, etc.)

Southeast corner of Section 5, Township 1 North, Range 5 East, Willamette Meridian.

118652

BOOK 141 PAGE 242

Skamania County Washington:

AUDITOR'S USE

Land Surveyor Information: (or Public Officer as per RCW 58.09.050)

This corner record correctly represents work performed by me or under by direction in conformance with the Survey Recording Act.

Company or agency:


Minister & Glaeser Surveying, Inc.

2208 E. Evergreen Blvd.

Vancouver, WA. 98661

Phone: (206) 694-3313

Fax: (206) 694-8410



Signature *Robert W. Glaeser* Date: 1/21/94 Seal:

Washington Plane Coordinates: N: _____ E: _____
Order: _____ Zone: _____ Datum (Date of adjustment): _____

Corner Information: Use the space below to provide the following information regarding the corner.

(1) Pertinent Corner History: The original survey was conducted by Deputy Surveyors, Lewis Van Vleet and John Newsom, under Contract No. 47, dated the 23rd day of April, 1859. The survey was conducted between April 26th and April 29th, 1859. Set a post common to Sections 4, 5, 8, and 9.

R.P.'s were as follows:

15" diameter Alder; North 63° West, 342 Links.

10" diameter Alder; South 38° West, 262 Links.

48" diameter Fir stub; South 50° East, 302 Links.

50" diameter Fir stub, North 35° East, 380 Links.

Skamania County Engineers records, shows finding said original survey marker, "X" on rock and old cedar post marking said corner. Referenced with Iron Fence post with Tag "X" 2 feet West of "X" on rock.

In August of 1973, W.F. Hagedorn conducted a survey (Book 1, page 6, of Skamania County records), shows finding stone with "X" and Iron Rod.

Registered _____
Indexed _____
Filed _____
Map _____

In January of 1974, Olson Engineering conducted a survey (Book 1, page 10, of Skamania County records), shows finding stone with "X" and Iron Rod.

(2) Evidence Found at the Corner: No original evidence found. Found and accepted the stone with "X" as the corner based on reputation and use.

(3) Corner Perpetuation Information:
Refer to the following records of surveys:

Surveys

Book 1, page 6
Book 1, page 10

	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
A																									
B																									
C																									
D																									
E																									
F																									
G																									
H																									
I																									
J																									
K																									
L																									
M																									
N																									
O																									
P																									
Q																									
R																									
S																									
T																									
U																									
V																									
W																									
X																									
Y																									
Z																									

RCM 58.07.065 (2) requires the following information on this form: an accurate description and location, in reference to the corner position, of all monuments and accessories (a) found at the corner and (b) placed or replaced at the corner; (c) basis of bearings used to describe or locate such monuments or accessories; and (d) corollary information that may be helpful to relocate or identify the corner position.

SPACE FOR ADDITIONAL COMMENTS