Seeley's Subdivision (R.4) Superior Su

access road

3/4"IP

TRAVERSE STATEMENT & SURVEY NARRATIVE: A closed field traverse for the parcel shown was made with a Sokkia five-second total station and related measuring equipment, all of which met State standards of WAC 332-130 at the time of this survey. Acceptable raw angular and distance closures in excess of 1:10000 were balanced by compass adjustment to effect mathematical closure. Physical appurtenances which may be in conflict with existing conditions or items of record are noted as shown. All corners indicated by a found 1/2" Iron pipe/plastic cap were set in 1980 for Reference 2.

Field work was conducted during the period of May 19 -October 4, 1999.

AUSPLUND ROAD CL

		AUSPLU	NU KUAU	CL	
Seg	Δ	R	L	Ch Brg	Dist
	CL/CL INT	χ			
L1	,			N 5'22'11"E	134.50
C1	22.07,00	286.50	10.59	N 1'02'48"W	109.90
L2				N12'06'18"W	39.40
C2	27"56'00"	229.20	111.74	N26'04'18"W	110.63
L3				N40°02'18"W	7.20
C3	63'52'00"	114.60	127.74	N 8'06'18"W	121.23
L4				N23'49'42"E	11.20
C4	31'03'00"	191.00	103.50	N 8°18′12″E	102.24
L5				N 7'13'18"W	59.90
C5	25'10'00"	191.00	83.89	N 5'21'42"E	83.22
L6				N17'56'42"E	29.80
C6	24.57.00	163.70	71.28	N 5'28'12"E	70.72
L7				N 7'00'18"W	34.20
C7	12.05,00,	191.00	40.28	N13'02'48"W	40.21
L8				N19'05'18"W	57.90
C8	22'17'00"	191.00	74.28	N30°13'48"W	73.82
L9	74170'00"	4.47.00	70.00	N41'22'18"W	30.90
C9	31°36'00"	143.20	78.98	N25°34′18″W	77.98
L10	4545755		04.00	N 9°46′18″W	61.50
C10	15'18'00"	229.20	61.20	N17°25'18"W	61.02
L11	0145170#	202 52	7.00	N25°04'18"W	55.50
C11	0°45'39"		3.80	N24'41'28"W	3.80
010	NE CORNE		-	N4 510010054	00.04
C12	17*52'21"	286.50	89.37	N15'22'28"W	89.01

REFERENCES:

- 1. Book 1, Page 259A of Surveys
- Book 1, Page 264 of Surveys
 Book 3, Page 88 of Short Plats
- 4. Book 1, Page 15 of Plats
- 5. Various County Road plan/profiles for roads shown

See R.2 for outline of R.4.

References listed are considered as part of this drawing and may provide survey information or detail not shown hereon.

Trantow Surveying makes no warranty as to matters of unwritten title such as adverse possession, estoppel, acquiescence, etc.; environmental concerns such as wetlands pollution, etc.; the accuracy or position of features shown without dimension.


TRANTOW SURVEYING, INC. 412 W. Jefferson-POB 287 Bingen, WA 98605-0287 Ph 509/493-3111 Fx 509/493-4309 Member of Land Surveyor's Assoc. of Washington

SURVEY FOR

DONALD KARI


SKAMANIA CO., WASHINGTON

Project #: <u>1682</u>



LEGEND

- Set 5/8"X30" iron rod w/1" red plastic cap
- Corner of record
- Calculated, not set or searched
- Call of record



(N86*59'48*W)

N86*49'03'W


327.76

S86°45'24'E

(\$86*56'24'E)

1/2"IP/PC

3/4"iP



3/4"IP

SURVEYOR'S CERTIFICATE

This map correctly represents a survey made by me or under my direction in conformance with the requirements of the Survey Recording Act at the request of Donald Kari in May, 1999.

Terry N. Trontow, PLS 15673

AUDITOR'S CERTIFICATE

Filed for record this 18th day of November, 1999 at 10:42 AM in Book 3 of SURVEYS at Page 322 at the request of Trantow Surv

County Auditor Deputy



5 oct. 1999