### I I I H SE1 品 K ÖRC C SE1 K R.5E., **14 OF SECTION** <mark>유</mark> 4 OF SECTION 19, SURVEY **≲ ≤** $\infty$

JONES: SMI/4 SMI/4 SECTION 18, T.2N., R.5E. SMITH: WARRENTY DEED BK. 76, P. 134

LEGAL DESCRIPTION

### REFERENCES

I. L.S. 9025 OLSON SURVEY, BK 1, P 213
2. L.S. 10997 GERMUNSON SURVEY, BK 2, P 50
2. L.S. 11989 LAWSON SURVEY, BK 2, P 211
3. L.S. 15024 GLAESER SURVEY, BK 2, P 211

N00 \*54 ' 07 "E

1323.85

S01 42 42 W

1318.99

N02 131 38E

1314.41

1345.96

1364.55

### NOTES

E SEARCH FOR GLO BT'S BUT NONE FOUND AS THEY ZERY SMALL DIAMETER TREES IN 1859 AND THE T BURN COVERED THIS AREA IN THE EARLY 1900'S. EAM NORTH OF THE SET CORNER FIT WITH IN 4 FEET SLO CALL FOR A BROOK AT 3.5 CHAINS. GLO FOR T.2N., R.5E., M.M. PAGES 55-57. FOUND OLD N-5 WIRE MOSTLY DOWN EAST OF MARKED LINE AS SHOWN.

- 2. JONES CONSTRUCTED MIRE FENCE MORE THAN 10 YEARS EARLIER MITHOUT THE BENEFIT OF A LAND SURVEY.
- 3. SUBSTANTIAL ENCROACHMENT OF PORTABLE ITEMS EXIST ALONG THE ACCESS ROAD TO THE MORRIS PROPERTY FROM THULA NARROWS THROUGH THE SMITH PROPERTY.

N00 \*54' 07 "E 1323.84'

501 °42 '42"W 1318.99

S02 31 38" 1314 41

**BASIS OF BEARING** 

THE EAST HALF OF THE SOUTH LINE OF SECTION 18 HELD AS 584°55'00"E AS PER REF. I

S89 \*55 '00 \*E 1327 . 38 '

N01 \*47 '52 \*E 440.00 '

NOTE 3

S01 \*02 '07 "W 655.56 '

657.06

NOTE 4

OLD DOWN MIRE FENCE WAS FOUND TO EXIST ALONG IST SIDE OF THE JONES PROPERTY. MIRE WAS FOUND IS SPORADICALLY EAST (1-5 FT) OF THE SOUTH PART OF P

# TRAVERSE & ACCURACY STATEMENT

SURVEY WAS MADE WITH A FIVE-SECOND TOTAL STATION AND RELATED MEASURING EQUIPMENT, OF WHICH MEET STATE STANDARDS (WAC 332-130-090,-100) AT THE TIME OF THIS SURVEY. ACCEPTABLE RAW ANGULAR AND DISTANCE CLOSURES NOT EXCEEDING 1:5000 MERE AQUIRED. NO ADJUSTMENT WAS NECESSARY TO EFFECT MATHEMATICAL CLOSURE.

## SURVEY NARRATIVE

The purpose of this survey is to locate the Jones property lines and the line between the Smith and Morris Properties. The SE Section 18 corner was set using the reference I survey proportioning. The reference 2 survey was used for Section 18 breakdown.

The reference 3 survey was used for Section 19 breakdown.

### EGEND

KER FOUND AS NOTED F. I SURVEY

1622.79

160.03

173.25 333.27 N89°47'00"W

SET 5/8 REBAR W YPC T-POST I' NORTH

S89 \*47 '04\*E 666.55'

S00 47 01 W

N89°47'15"W

- CUILATED CORNER;
  I SET OR FOUND.
  AT OR DEED CALL ITING FENCE LINES
- ROX. LOCATION OF THUJA NARROWS YELLOW PLASTIC CAP ON 5/8" REBAR 6 MARKED WITH T-POSTS
- 2-1/2" ALUMINIM CAP ON 5/8" REBAR

## -02


## **AUDITOR'S CERTIFICATE**

Filed for record this 30<sup>+k</sup> day of January, 2001 at 10:06 1M in Book 3 of Surveys at page 420 at the request of Bell Design Co.

Michael Harrison by Powery Lepute,

## SURVEYOR'S CERTIFICATE

This map correctly represents a survey made by me or under my direction in conformance with the current requirements of the Survey Recording Act at the request of Saille Jones and David Smith



akes no warranty as to matters of unwritten title such as adverse possesion, prescriptive estoppel, acquiescence, etc. or to environmental concerns such as hazardous waste, delineation, riparian changes, flood zones, etc. GRAPHIC SCALE

FOR SALLIE JONES AND DAVID SMITH COUNTY. WASHINGTON SURVEY

DATE:Jan_2002	PROJECT: 01B040	SHEET:1 OF1

### COMPAINY DESI

19

20

CENTER OF L SECTION 19 CALC. AS PER REF. 3

1491.60

M.6E.EZ.68N

S01 \*47 '52 "W

.6E.68N

S01 \*17 '18 "W

654.08

655.56

S01 \*02 '07 "W

657.06

1622.79

1379.34

1487.52' 39°39'11"W

1314.13

wet land

makes no

487

22



SKAMANIA