

Stateform Fax:

877-449-5784



Doc# 2004154403

Page 1 of 6

Date: 09/09/2004 01:15P

Filed by: SKAMANIA COUNTY

Filed & Recorded in Official Records

of SKAMANIA COUNTY

J. MICHAEL GARVISON

AUDITOR

Fee: \$0.00

Claim # 474537251

### SKAMANIA COUNTY CLAIM FOR DAMAGE FORM

**CLAIMANT: THIS CLAIM MUST BE FILED WITH THE**

SKAMANIA COUNTY CLERK OF THE BOARD  
Skamania County Auditor's Office  
Skamania County Courthouse  
240 North West Vancouver Avenue, Room 27  
Stevenson, WA 98648

**FOR OFFICE USE ONLY:**

CLAIM NO. \_\_\_\_\_

DATE FILED: \_\_\_\_\_

COPIES TO: \_\_\_\_\_

**NO DAMAGES CAN BE PAID BY SKAMANIA COUNTY UNLESS THIS FORM IS COMPLETE. THIS PROVISION CANNOT BE WAIVED.**

ATTACHMENTS: YES( # ) NO

1. Name (including spouse if married): (Please Print)

Rebecca L. Zitter

2. 3201 Hst Washougal WA 98671  
Address City State Zip

3. HM Phone: 3608353109 WK Phone: 3608359518 MSSG Phone: \_\_\_\_\_

4. Date and time of incident: 8/29 around 1:30 - 2:00 pm?

5. Location of incident:

Skamania County Hwy 14

6. Describe in narrative form and in detail exactly how the incident occurred:

The Sheriff pulled out in front of me to pull a U turn and pull over a vehicle in the opposite lane for speeding. I did not have time to stop and unfortunately hit the officer in the rear drivers side.

7. What is the amount of damages claimed arising out of the following circumstances

(Include estimates and bills, if available): Contact State Farm

\*also Contact State Farm. for copies of estimates.

Claim 474537251

8. Please list name and address of any and all witnesses or persons involved:  
(Please Print)

Contact Skamania County

9. Describe the damages or injuries you sustained as a result of the incident:

hand (left), neck, back

10. Was incident investigated by a police officer? Sheriff \_\_\_\_\_ State Patrol ☒ City Washington State

11. If a vehicle was involved in the incident, describe: Make VW  
Model Jetta TDI Year 2001 State WA License No. 7  
Insurance Company Statefarm Policy Number LO4-1347-829-478

12. Describe what you did after the incident occurred: Went to the E.R.

13. Describe the conversations you had, if any, with County personnel during or after the incident occurred. Described to the investigating officer (I think) what happened.

14. How did you identify the County as the party responsible for your damage?

The investigating officer identified the County responsible, I did not.

I certify under penalty of perjury under the laws of the State of Washington that the information contained in this claim is true and correct.

DATED THIS 7<sup>th</sup> DAY OF September, 2004

  
Claimant's Signature

File Name: Commiss/Risk Mang/Claims/Claim For Damages

**NOTE:** Personal property (car, etc.) damages are to be accompanied by 2 estimates for repair costs. The Skamania County Risk Manager will investigate this claim. The decision to honor this claim will be based upon that investigation. Making a false report or providing false evidence is a crime and punishable by fine and/or imprisonment. Additional pages may be attached if needed to answer the questions.

09/02/2004 at 09:45 AM  
78285

Job Number:

*509-427-7345*

**CHUCK'S AUTO BODY**  
YOU'VE HAD ONE ACCIDENT-NOW MAKE THE RIGHT CHOICE  
415 22ND ST.  
WASHOUGAL, WA 98671  
(360)835-5515 Fax: (360)835-7708

**ESTIMATE OF RECORD**

Written By: Tom Howard 09/02/2004 09:44 AM  
Adjuster: CD-Tm14 Claim Rep (253)473-8264

**Insured:** BECKY RITTER  
**Owner:** BECKY RITTER  
**Address:** 3201 H ST  
WASHOUGAL, WA 98671-1910  
**Evening:** (360)835-5409

**Claim #**47-4537-25101  
**Policy #**  
**Deductible:** \$500.00  
**Date of Loss:** 08/29/2004 at 02:00 PM  
**Type of Loss:** Comprehensive  
**Point of Impact:**

**Inspect**  
**Location:** CHUCKS AUTO

**Day:** ()-

**Insurance** STATE FARM INSURANCE COMPANIES  
**Company:** 4600 25TH AVENUE NORTHEAST  
SALEM, WA 97313

**Business:** (253)473-8264  
**Days to Repair**

2001 VW JETTA GL TDI 4-1.9L-TD 4D SED black Int:

**VIN:** 3VWRP29MX1M042823 **Lic:** 948rin **WA** **Prod Date:** **Odometer:** 90858

Air Conditioning	Rear Defogger	Tilt Wheel
Cruise Control	Telescopic Wheel	Intermittent Wipers
Keyless Entry	Theft Deterrent/Alarm	Body Side Moldings
Dual Mirrors	Clear Coat Paint	Power Steering
Power Brakes	Power Locks	Power Mirrors
Anti-Lock Brakes (4)	Driver Air Bag	Passenger Air Bag
Front Side Impact Air Bag	4 Wheel Disc Brakes	Cloth Seats
Bucket Seats	Recline/Lounge Seats	<i>AUTOMATIC Transmission</i>

NO.	OP.	DESCRIPTION	QTY	EXT.	PRICE	LABOR	PAINT
1		HOOD					
N 2	Repl	Hood	1	376.98		1.3	2.6
3		Add for Clear Coat					1.0
4		Add for Underside(Complete)					1.3
5		Add for Clear Coat					0.3
6		FRONT BUMPER					
7		O/H front bumper				1.5	
8**	Repl	RECOND Bumper cover	1	194.00		Incl.	2.4
9		Add for Clear Coat					1.0
10	Repl	Impact bar	1	113.20		Incl.	
11	Repl	Absorber	1	49.57		Incl.	
12	Repl	RT Grille outer	1	6.65		Incl.	
13	Repl	LT Grille outer	1	9.20		Incl.	
14	Repl	Grille center	1	25.37		Incl.	
15	Repl	LT Side support	1	6.65		Incl.	

**ESTIMATE OF RECORD**

2001 VW JETTA GL TDI 4-1.9L-TD 4D SED black Int:

NO.	OP.	DESCRIPTION	QTY	EXT. PRICE	LABOR	PAINT
16		FRONT LAMPS				
17	Repl	LT Headlamp assy GL & GLS	1	167.10	Incl.	
18		Aim headlamps			0.5	
19	Repl	LT Marker lamp assy	1	9.20	Incl.	
20		GRILLE				
21	Repl	Grille assy	1	101.33	Incl.	0.6
22		Overlap Minor Panel				-0.2
23		Add for Clear Coat				0.1
24		COOLING				
25*	Repl	Radiator support	1	223.27	3.8	<u>0.0</u>
26		Evacuate & recharge			m 1.4	M
27		Refrigerant recovery			m 0.4	M
28	Repl	Sight shield	1	3.68	0.2	
29	Repl	Intake duct	1	4.30	0.2	
30	Repl	Air deflector	1	3.88	0.2	
31**	Repl	A/M Radiator	1	214.47	4.4	
32		Deduct for Overlap			-3.0	
33		FENDER				
34	Repl	LT Fender sedan	1	199.38	1.5	2.2
35		Overlap Major Adj. Panel				-0.4
36		Add for Clear Coat				0.4
37		Add for Edging				0.5
38		Add for Clear Coat				0.1
39	Repl	LT Fender liner	1	23.50	Incl.	
40	Repl	LT Upper rail	1	57.38	s 2.5	0.8
41	Repl	LT Cover plate sedan	1	51.72	s 1.0	
42*	Rpr	LT Apron assy sedan			s 3.0	1.2
43		Overlap Minor Panel				-0.2
44*	Rpr	LT Side rail assy			s 2.0	<u>0.6</u>
45		Overlap Major Adj. Panel				-0.4
46		ELECTRICAL				
47	Repl	Side cover	1	9.37		
48		RESTRAINT SYSTEMS				
49	Repl	Driver air bag w/3 spoke wheel	1	688.48	m Incl.	
50		System diagnosis			0.5	
51	Repl	Control module	1	504.33	m 1.2	M
52	Repl	Clockspring w/o steering sensor	1	50.23	m 1.0	M
53	Repl	Psngr air bag	1	304.70	m 0.8	M
54	Repl	RT Sensor lateral impact	1	142.55		
55	Repl	LT Sensor lateral impact	1	142.55		
56	Repl	LT Retractor assy sedan black	1	143.07	0.6	
57		FRONT DOOR				
58*	Rpr	LT Door shell			<u>6.0</u>	2.0
59		Overlap Major Adj. Panel				-0.4
60		Add for Clear Coat				0.3
61*	R&I	LT Body side mldg black			<u>0.4</u>	
62	R&I	LT R&I mirror			0.4	

**ESTIMATE OF RECORD**

2001 VW JETTA GL TDI 4-1.9L-TD 4D SED black Int:

NO.	OP.	DESCRIPTION	QTY	EXT. PRICE	LABOR	PAINT
63*	R&I	LT Window guide			0.3	
64	R&I	LT Door glass NAGS			0.7	
65	R&I	LT Handle, outside black			0.3	
66	R&I	LT R&I trim panel			0.4	
67		WINDSHIELD				
68	Repl	Windshield Volkswagen, sedan w/o rain sensor	1	190.93	2.8	
69#		SEAL KIT	1	25.00		
70#		TINT COLOR	1		0.5	
71#		COVER CAR	1	5.00	0.3	
72#		WASTE DISPOSAL	1	3.00		
73#		CORROSION PROTECTION	1			0.6
74		AIR CONDITIONER & HEATER				
75**	Repl	A/M Condenser	1	175.00	3.5	
76		Deduct for Overlap			-2.9	
Subtotals ==>				4225.04	37.7	16.4

Line 2 : NO LKQ PARTS AT THIS TIME FROM FAP, ROSE OR PORTLAND IMPORTS

Parts		4225.04
Body Labor	32.9 hrs @ \$ 44.00/hr	1447.60
Paint Labor	16.4 hrs @ \$ 44.00/hr	721.60
Mechanical Labor	4.8 hrs @ \$ 60.00/hr	288.00
Paint Supplies	16.4 hrs @ \$ 22.00/hr	360.80
Body Supplies	36.0 hrs @ \$ 1.00/hr	36.00
SUBTOTAL		\$ 7079.04
Sales Tax	\$ 7079.04 @ 7.9000%	559.24
GRAND TOTAL		\$ 7638.28
ADJUSTMENTS:		
Deductible		500.00
CUSTOMER PAY		\$ 500.00
INSURANCE PAY		\$ 7138.28

CHUCKS AUTO BODY WARRANTIES WORKMANSHIP AND REFINISH MATERIALS FOR THE LIFETIME OF THE VEHICLE, OR AS LONG AS CUSTOMER MAINTAINS OWNERSHIP. PARTS ARE WARRANTIED FOR A YEAR OR AS OTHERWISE SPECIFIED BY MANUFACTURER.

09/02/2004 at 09:45 AM  
78285

Job Number:

**ESTIMATE OF RECORD**

2001 VW JETTA GL TDI 4-1.9L-TD 4D SED black Int:

Estimate based on MOTOR CRASH ESTIMATING GUIDE. Unless otherwise noted all items are derived from the Guide ERA9277 Database Date 07/2004, CCC Data Date 07/2004, and the parts selected are OEM-parts manufactured by the vehicles Original Equipment Manufacturer. OEM parts are available at OE/Vehicle dealerships. Asterisk (\*) or Double Asterisk (\*\*) indicates that the parts and/or labor information provided by MOTOR may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. Non-Original Equipment Manufacturer aftermarket parts are described as AM, Qual Repl Parts or Comp Repl Parts which stands for Competitive Replacement Parts. Used parts are described as LKQ, Qual Recy Parts, RCY, or USED. Reconditioned parts are described as Recon. Recored parts are described as Recore. NAGS Part Numbers and Prices are provided by National Auto Glass Specifications, Inc. Pound sign (#) items indicate manual entries.

CCC Pathways - A product of CCC Information Services Inc.

Unofficial Copy

DOC # 2004154403  
Page 6 of 6