
## SURVEY in NW%NW% Sec.

TRAVERSE STATEMENT: A closed field traverse for the parcel shown was made with a 10-second total station and related measuring equipment, all of which met State standards of WAC 332-130 at the time of this survey. Acceptable raw angular and distance closures in excess of 1:10000 required no adjustments. Physical appurtenances which may be in conflict with existing conditions or items of record are noted or depicted. The intent of this project in 1997 was to create a two-lot short plat of the W½ NE¼ NW¼ NW¼.

SURVEY NARRATIVE: Field work was conducted duri short plat was cancelled by Skamania County due we made a brief field inspection in August, 2004 t ing April—August of 1997 and monuments were set, but the to lack of commitment by the landowner. At client request, to update improvements.





• UP

Electric vault

Utility pole

m

Electric line Fenceline 0

Monument of record

Calculated for dimensions

Set 5/8"X30" iron rod w/1" red plastic cap

LEGEND

SCALE 1" = 100 FEET

8

TRANTOW SURVEYING, INC.
412 W. Jefferson-POB 287
Blingen, WA 98605-0287
Ph 509/493-3111 Fx 509/493-4309
Member of Land Surveyor's Assoc. of Washington

Deed references: B.61, B.61,

P.655 Angus to Guest P.656 C.M. Angus to C.I. Angus

REFERENCES (those listed are considered as part of this drawing and may provide survey information or detail not shown hereon):

1. B.3, P.145 of Short Plats, AF# 142832 (11/2001)
Basis of bearings: Reference 1

SURVEY FOR

CHARLES MARIE ANGUS BASS

SKAMANIA CO.,

Copyright 2004

**#**2300 WASHINGTON

SURVEYOR'S C ERTIFICATE

This map correctly represents a survey made by direction in conformance with the requirements o Recording Act at the epresents a survey made by me or under my ince with the requirements of the Survey request of Charles Angus in April, 1997.

9-8-04

CERTIFICATE

request of Trantow Surveying. recorded by AF# 2004154471 Filed for record this day of Supt. . 2004 ot 4:54 pm in Surveys at the

Muchael Darnson