


LAND CORNER RECORD

GRANTOR/SURVEYOR/PUBLIC OFFICER: This corner record correctly represents work performed by me or under my direction, in conformance with the Survey Recording Act.

COMPANY OR AGENCY: USDA Forest Service
Gifford Pinchot National Forest
10600 NE 51st Circle
ADDRESS: Vancouver WA 98682



Don Karsch 9/01/2004
Forest Land Surveyor Date

GRANTEE: PUBLIC **SEAL/SIGNATURE/DATE**
LEGAL: W.C. W1/16 S23 TWP: 4 NORTH RGE: 7 EAST CORNER CODE: N18

ADDITIONAL IDENTIFIER: BLM designation, street, or plat names, block, lot, etc.

COUNTY: SKAMANIA
WASHINGTON PLANE COORDINATES: N: E:

ORDER: ZONE: DATUM: (DATE OF ADJUSTMENT):
CORNER INFORMATION: Discuss the history, evidence found, and perpetuation of the corner. Diagram the references; provide the date of work; and if applicable, a reference to a map of record and/or the field book/page no. Use the back, if needed.

Corner History:

This corner was originally established by Roy Gaylord, PLS#18731, in July of 1983. He set a 2 1/2" by 30" aluminum pipe with a 2 1/2" aluminum cap, tagged, painted, and scribed two bearing trees:

- A 12" Maple - N2°W, 153.3 ft., bark scribed "X BT."
- A 19" Maple - N13°E, 151.2 ft., bark scribed "X BT."

On September 6, 2004 I searched for and found the witness corner monument, in good condition, about 12" below the sand and dirt. The corner sits in old flood plain due west from bend in river.

Found BT's:

- A 12" now 20" Twin Maple - live with visible bark scribe bears N2°W, 153.3 ft. Attention sign found at base of tree.
- A 20" dead alder snag, called by Gaylord 19" Maple, bears N13°E, 151.2 ft., bark scribing visible and BT tag present.

New BT's established:

An 11" Cottonwood tree bearing S80°W, 25.70 ft. scribed "X", "X BT". Placed BT tag and land survey monument sign on BT, as well as, washer in tree face, and nail at side center.


Forest service property lines leading north and south from the W 1/16 corner position are brushed, blazed, painted, and posted w/USFS carsonite posts. Bearings are by compass w/18° East declination. Distances are to side center nail in bearing tree.

Witnessed by: Georgene Wheatley, LSIT #74341

MARK THE CORNER LOCATION BELOW AND FILL IN THE CORNER CODE BLANK ON THE OTHER SIDE:
For corners at the intersection of two lines, the corner code is the alphanumeric coordinate that corresponds to the appropriate intersection of lines.


For corners that are only on one line, the corner code is the line designation and the related line segment; i.e., a corner on line 5 between 'B' and 'C' is designated BC-5.

For corners that are between lines, the corner code is both line segments; i.e., a corner in the SE1/4 of the SE1/4 of section 18 is designated MN 4-5.



RCW 58.09.060 (2) requires the following information on this form: an accurate description and location, in reference to the corner position, of all monuments and accessories (a) found at the corner and (b) placed or replaced at the corner; (c) basis of bearings used to describe or locate such monuments or accessories; and (d) corollary information that may be helpful to relocate or identify the corner position.

SPACE FOR ADDITIONAL COMMENT:



Found 2½" x 30" aluminum pipe w/ 2½" aluminum cap, in good condition, about 12" below the Sand and dirt.