

## SURVEY in SW%SW% Sec. 13N, R9E, W.M.

Tax Parcel No. 03-09-11-0-3-0600-00



TRAVERSE STATEMENT: A closed field traverse for the parcel shown was made with a Sokkia Set—3100 total station and related measuring equipment, all of which met State standards of WAC 332—130 at the time of this survey.

SURVEY NARRATIVE: The purpose of this project was to monument the parcel as a condition of sale. All monuments were set out 30 feet from the centerline of adjacent rights—of—way. Field work was conducted during the period of July 19—28, 2005.



REFERENCES (those listed are considered as part of this drawing and may provide survey information or detail not shown hereon):

1. B.1, P.240 of Surveys, AF#90885

2. B.3, P.279 of Short Plats, AF#123854

3. B.3, P.385 of Short Plats, AF#141232

Basis of bearings taken from Reference 3.

Trantow Surveying makes no warranty as to matters of unwritten title; environmental concerns; the accuracy or position of features shown without dimension.

Call of record

TRANTOW SURVEYING, INC.
412 W. Jefferson-P0B 287
Bingen, WA 98605-0287
Ph 509/493-3111 Fx 509/493-4309
Member of Land Surveyor's Assoc. of Washington

SURVEY FOR

## DARLENE BA/RD

SKAMANIA CO., WASHINGTON

#2399 Copyright 2005

₹



SURV EYOR'S CERTIFICATE

This map correctly direction in confor Recording Act at represents a survey made by me or under my nance with the requirements of the Survey ne request of Darlene Baird in July, 2005.

8/2/05 Date

AUDITOR'S CERTIFICATE

Filed for record this 3nd request of Trantow Surveying. recorded by AF#\_ 3<u>m</u> day of <u>AUGUS</u>t, 2005 at <u>10:54</u> AM 2005/582/1

J. Michael Larvison by Deputy Auditor