
SURVEY in W1/2SW1/4 Sec. 11, T2N, R7E, W.M.

2006160200



0

TRAVERSE STATEMENT: A point to point field traverse for the parcel shown was made with a Sokkia total station and related measuring equipment, all of which met State standards of WAC 332—130 at the time of this survey. Radial ties were made to monuments of record which provided the best evidence of the line to be flagged, painted and blazed.

SURVEY NARRATIVE: Field work was conducted during the period of November 10 — January 3, 2006, the purpose of which was to mark the indicated lines to allow for timber harvesting. No monument could be found at the Southerly end of the marked line, and the record is unclear if such had ever been established. The point falls in a gully filled with a considerable number of jackstrawed windfalls. A monument was established on the South line of Section 11, West of the top of the gully.

REFERENCES (those listed are considered as part of this drawing and may provide survey information or detail not shown hereon):

1. B.1, P.18—19 of Surveys, AF#77703—77704
Basis of bearings taken from Ref. 1 as indicated.



SURVEYOR'S CERTIFICATE

This map correctly represents a survey made by me or undermy direction in conformance with the requirements of the Survey Recording Act at the request of Pacific Forest Consultants in July, 2005.

ry N. Tromow, 1/09/06 Date

AUDITOR'S CERTIFICATE

Filed for record this $11^{+/4}$ day of $\sqrt{3:28}$ pm recorded by AF# 2006160200 in Surveys at the

PACIFIC

#2440

request of Trantow Surveying. County Auditor Deputy Deputy