

SKAMANIA COUNTY CLAIM FOR DAMAGE FORM

CLAIMANT: THIS CLAIM MUST BE FILED WITH THE

SKAMANIA COUNTY CLERK OF THE BOARD
Skamania County Auditor's Office
Skamania County Courthouse
240 North West Vancouver Avenue, Room 27
Stevenson, WA 98648

FOR OFFICE USE ONLY:

CLAIM NO. _____

DATE FILED: _____

COPIES TO: _____

NO DAMAGES CAN BE PAID BY SKAMANIA COUNTY UNLESS THIS
FORM IS COMPLETE. THIS PROVISION CANNOT BE WAIVED.

ATTACHMENTS: YES(#) NO

1. Name (including spouse if married): (Please Print)

Darren Gallion

2. 121 Coho Loop COOK WA 98605
Address City State Zip

3. HM Phone: 541-380-1122 WK Phone: 360-604-2880 MSSG Phone: _____

4. Date and time of incident: 8:30 am 3/8/2006

5. Location of incident:

Cook Underwood Rd

6. Describe in narrative form and in detail exactly how the incident occurred:

The Skamania Co Rd crew was cleaning rocks from
the ditch to Roadway. I was parked waiting for
to be signaled through. A plow truck had just cleared
rocks from the road when it backed into my car

7. What is the amount of damages claimed arising out of the following circumstances

(Include estimates and bills, if available): \$1548.89

There could be additional damage that currently isn't visible

8. Please list name and address of any and all witnesses or persons involved:
(Please Print)

County personnel

9. Describe the damages or injuries you sustained as a result of the incident: Visible

Damage is identified in "Leifs" estimate

10. Was incident investigated by a police officer? Sheriff _____ State Patrol _____
City _____
NO

11. If a vehicle was involved in the incident, describe: Make _____
Model _____ Year _____ State _____ License No. _____
Insurance Company _____ Policy Number _____

12. Describe what you did after the incident occurred: Road Crew Supervisor
took pictures and directed me to the public works
superintendent, who then referred me to the Sk. County
Auditors office for forms

13. Describe the conversations you had, if any, with County personnel during or after the incident occurred. County personnel instructed me to fill out
forms and I would get reimbursed

14. How did you identify the County as the party responsible for your damage?

Vehicle emblems, spoke with personnel

I certify under penalty of perjury under the laws of the State of Washington that the information contained in this claim is true and correct.

DATED THIS 9th DAY OF March, 2006


Claimant's Signature

File Name: Commis/Risk Mang/Claims/Claim For Damages

NOTE: Personal property (car, etc.) damages are to be accompanied by 2 estimates for repair costs. The Skamania County Risk Manager will investigate this claim. The decision to honor this claim will be based upon that investigation. Making a false report or providing false evidence is a crime and punishable by fine and/or imprisonment. Additional pages may be attached if needed to answer the questions.

LEIF'S AUTO COLLISION CENTER - WESTSIDE
14280 SW 72ND AVE.
TIGARD, OR 97224
(503) 620-5343 FAX: (503) 968-3191

CD LOG NO 39144-1 DATE 03/08/06

SHOP: LEIF'S AUTO COLLISION CENTER INSP DATE: 03/08/06
ADDRESS: 14280 S.W. 72ND AVE. CONTACT: KEVIN TIPPIT
CITY STATE: TIGARD, OR PHONE 1: (503) 620-5343
ZIP: 97224- FAX: (503) 968-3191

OWNER: GALLION, DARREN

POINT OF IMPACT: 3

LIC#: STATE: VIN: 3VWSP69M22M060968
BODY COLOR: MILEAGE:
CONDITION: ACCTNG CTL#:

=USER-ENTERED VALUE E=REPLACE OEM NG=REPLACE NAGS
EC=REPLACE ECONOMY UE=REPLACE OE SURPLUS UC=RECONDITIONED PRT
JM=REMAN/REBUILT PRT EU=REPLACE SALVAGE EP=REPLACE PXN
OE=REPLACE PXN OE SRPLS PC=PXN RECONDITIONED PM=PXN REMAN/REBUILT
PE=PARTL REPL PRICE ET=PARTL REPL LABOR IT=PARTIAL REPAIR
R=REPAIR L=REFINISH BR=BLEND REFINISH
RT=TWO-TONE CG=CHIPGUARD SB=SUBLET
N=ADDITIONAL LABOR RI=R&I ASSEMBLY P=CHECK
AA=APPEAR ALLOWANCE RP=RELATED PRIOR UP=UNRELATED PRIOR

VEHICLE NEEDS DAMAGED PARTS REMOVED FOR COMPLETE ESTIMATE
THIS IS NOT A COMPLETE ESTIMATE.

2002 VOLKSWAGEN JETTA GLS TDI 4DOOR SEDAN 4CYL DIESEL TURBO 1.9
CODE: 61633B/D OPTNS F/24DKBCG

OPTIONS:
TWO-STAGE - EXTERIOR SURFACES TWO-STAGE - INTERIOR SURFACES
POWER WINDOWS CRUISE CONTROL
HEATED REMOTE CONTROL MIRRORS POWER DOOR LOCKS
AIR CONDITIONING

OP	GDE	MC	DESCRIPTION	MFG.PART NO.	PRICE	AJ%	B%	HOURS
1	0004		FRT BUMPER CVR OVERHAU	ADDNL LABOR OPERA				2.0
1	0006		COVER, FRONT BUMPER	1J5807217JGRU	296.52			INC 1
1	0006	13	COVER, FRONT BUMPER	REFINISH				3.5
			2.4 SURFACE					
			0.6 TWO STAGE SETUP					
			0.5 TWO STAGE					
1	0012		GRILLE, FRT BMPR CVR LT	1J5853665BB41	9.15			INC 1
1	0013		GRILLE, FRT BMPR CVR RT	1J5853666BB41	9.15			INC 1
1	0016		GRILLE, FRT BMPR CVR	1J5853677CB41	36.67			INC 1

2002 VOLKSWAGEN JETTA GLS TDI 4DOOR SEDAN
CD LOG NO 39144-1

E	0019	MLDG, FRT BMPR CVR LWR	1J5807719FGRU	100.10	INC 1
J	0019	MLDG, FRT BMPR CVR LWR	REFINISH		0.8 4
			0.7 SURFACE		
			0.1 TWO STAGE		
E	0010	SPOILER, LOWER FRONT	1J5805903BB41	60.10	INC 1
RI	0008	BRKT, FRONT LIC PLATE	R&I ASSEMBLY		0.2 1
E	0007	ABSORBER, FRONT BUMPER	1J0807248A	71.35	INC 1
E	0030	MLDG, GRILLE UPPER	1J5853655C01C	45.57	0.2 1
E	0031	EMBLEM, GRILLE	1J5853601FDY	31.93	0.2 1
E	0042 01	HEADLAMP ASSY, HALOG RT	1J5941018BJ	175.25	0.2 1
J	0973	HEADLAMPS AIM	ADDNL LABOR OPERA		0.4 1
J	M14	CORROSION PROTECTION	REFINISH		0.5*4
J	M15	COLOR TINT	REFINISH		0.5*4
3B	M17	COVER CAR EXTERIOR	SUBLET REPAIR	10.00*	4
3B	M60	HAZARD. WSTE. REM.	SUBLET REPAIR	5.50*	1
3B		DENIB & POLISH 1 PANEL	SUBLET REPAIR	5.00*	0.5*1
E		front bra	NEW PART	150.00*	0.2*1

21 ITEMS

MC MESSAGE(S)

01 CALL DEALER FOR EXACT PART NUMBER / PRICE

13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

FINAL CALCULATIONS & ENTRIES

GROSS PARTS	985.79
PAINT MATERIAL	137.80
PARTS & MATERIAL TOTAL	1,123.59

LABOR	RATE	REPLACE HRS	REPAIR HRS	
1-SHEET METAL	44.00	1.0	2.9	171.60
2-MECH/ELEC	70.00			
3-FRAME	55.00			
4-REFINISH	44.00	5.3		233.20
5-PAINT MATERIAL	26.00			
LABOR TOTAL				404.80
SUBLET REPAIRS				20.50
TOWING				
STORAGE				

GROSS TOTAL 1,548.89

JET TOTAL 1,548.89

ADP SHOPLINK U9784 ES CD LOG 39144-1 DATE 03/08/06 12:58:22AM R6.37 CD 02/06

PXN: Y/00/00/00/00/00 CUM 00/00/00/00/00 GEOCODE 97224

HOST LOG

(C) 1998 - 2005 ADP CLAIMS SOLUTIONS GROUP, INC.

..2 HRS WERE ADDED TO THIS EST. BASED ON ADP TWO-STAGE REFINISH FORMULA.

2002 VOLKSWAGEN JETTA GLS TDI 4DOOR SEDAN
CD LOG NO 39144-1

BODY & PAINT RATE AS OF MAY 1ST 2005 IS \$44.00 PER HOUR.
MECH. RATE IS \$70.00 PER HOUR.
FRAME RATE AS OF MAY 1ST IS \$55.00 PER HOUR.
BODY REPAIR MATERIALS @ \$6.00 PER REPAIR & WELDED HOUR.
PAINT MATERIALS AS OF MAY 1ST @ \$26.00 PER HOUR PER REFINISH HOUR.
NO DENIALS OR RATE CHANGES WILL BE ACCEPTED
AFTER REPAIRS HAVE BEEN NEGOTIATED AT THE SHOP
-----FOR ALL INSURANCE PAYMENTS-----
JEIFS AUTO COLLISION CENTERS NEEDS TO KNOW
WHERE IS THE CHECK BEING SENT TO _____
WHEN WILL THE CHECK BE SENT _____

*Rec
Bumper = \$200 P+L
If Damaged.*

DC # 2006160787
Page 5 of 7

03/08/2006 at 10:26 AM
23878

Job Number:

HANNAH COLLISION CENTER
Federal ID #:910296290
HANNAH COLLISION CENTER
3517 NE Auto Mall Drive
PO Box 1679
Vancouver, WA 98668
(800)541-3088 Fax: (360)256-2608

PRELIMINARY ESTIMATE

Written By: Jim Bowen
Adjuster:

Insured: Darren Gallion
Owner: Darren Gallion
Address: 121 Coho Loop
Cook, WA 98605
Day: (541)380-1122

Claim #
Policy #
Deductible:
Date of Loss:
Type of Loss:
Point of Impact: 12. Front

Inspect
Location:

Insurance
Company:

Days to Repair

2002 VW JETTA GLS TDI 4-1.9L-TD 4D SED RED CC Int:

VIN: 3VWSP69M22M060968 **Lic:** 495-NTX **WA** **Prod Date:**

Odometer:

Air Conditioning	Rear Defogger	Tilt Wheel
Cruise Control	Telescopic Wheel	Intermittent Wipers
Keyless Entry	Theft Deterrent/Alarm	Body Side Moldings
Dual Mirrors	Clear Coat Paint	Power Steering
Power Brakes	Power Windows	Power Locks
Power Mirrors	AM Radio	FM Radio
Stereo	Cassette	Search/Seek
CD Player	Anti-Lock Brakes (4)	Driver Air Bag
Passenger Air Bag	Front Side Impact Air Bag	4 Wheel Disc Brakes
Cloth Seats	Bucket Seats	5 Speed Transmission
Overdrive		

NO.	OP.	DESCRIPTION	QTY	EXT.	PRICE	LABOR	PAINT
1		FRONT BUMPER					
2		O/H front bumper	0		0.00	1.5	0.0
3	Repl	Bumper cover	1		296.52	Incl.	2.4
4		Add for Clear Coat	0		0.00	0.0	1.0
5	Repl	Cover molding	1		100.10	Incl.	0.5
6	Repl	Impact bar	1		145.37	Incl.	0.0
7	Repl	Absorber	1		71.35	Incl.	0.0
8#	Rpr	TINT COLOR	0		0.00	0.5	0.0
9#	Subl	Flex Additive	1		7.50 T	0.0	0.0
10#	Repl	Front Bra	1		150.00	1.0	0.0

03/08/2006 at 10:26 AM
23878

Job Number:

PRELIMINARY ESTIMATE

2002 VW JETTA GLS TDI 4-1.9L-TD 4D SED RED CC Int:

NO.	OP.	DESCRIPTION	QTY EXT.	PRICE LABOR	PAINT
Subtotals ==>			770.84	3.0	3.9
Parts					763.34
Body Labor			3.0 hrs @ \$ 46.00/hr		138.00
Paint Labor			3.9 hrs @ \$ 46.00/hr		179.40
Paint Supplies			3.9 hrs @ \$ 26.00/hr		101.40
Sublet/Misc.					7.50
SUBTOTAL					\$ 1189.64
Sales Tax			\$ 1189.64 @ 8.1000%		96.36
GRAND TOTAL					\$ 1286.00

Does not include Headlap or Hood Adjustment

This is a visual estimate only and not a guaranteed bid. Any additional damage noted after disassembly may result in additional parts and/or labor charges. All parts are subject to invoice.

Estimate based on MOTOR CRASH ESTIMATING GUIDE. Unless otherwise noted all items are derived from the Guide ERA9277 Database Date 02/2006, CCC Data Date 02/2006, and the parts selected are OEM-parts manufactured by the vehicles Original Equipment Manufacturer. OEM parts are available at OE/Vehicle dealerships. OPT OEM (Optional OEM) parts are OEM parts that may be provided by or through alternate sources other than the OE/Vehicle dealerships. OPT OEM parts may reflect some specific, special, or unique pricing or discount. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor information provided by MOTOR may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. Non-Original Equipment Manufacturer aftermarket parts are described as AM, Qual Repl Parts or Comp Repl Parts which stands for Competitive Replacement Parts. Used parts are described as LKQ, Qual Recy Parts, RCY, or USED. Reconditioned parts are described as Recon. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries. Some 2006 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The Pathways estimator has a complete list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

CCC Pathways - A product of CCC Information Services Inc.