

SKAMANIA COUNTY CLAIM FOR DAMAGE FORM

CLAIMANT: THIS CLAIM MUST BE FILED WITH THE

SKAMANIA COUNTY AUDITOR'S OFFICE
Skamania County Courthouse
P.O. Box 790
240 NW Vancouver Avenue, Room 27
Stevenson, WA 98648

FOR OFFICE USE ONLY:

CLAIM NO. _____

DATE FILED: _____

COPIES TO: _____

NO DAMAGES CAN BE PAID BY SKAMANIA COUNTY UNLESS THIS FORM IS COMPLETE. THIS PROVISION CANNOT BE WAIVED.

ATTACHMENTS: YES(#) NO

1. Name (including spouse if married): (Please Print)
Sarah Harrington
2. 3218 NW 122nd St Vancouver WA 98685
Address City State Zip
3. HM Phone: cell 503 740 3115 WK Phone: N/A MSSG Phone: _____
4. Date and time of incident: Jan. 11th 2009, 10pm
5. Location of incident:
Stevenson, WA @ gas station
6. Describe in narrative form and in detail exactly how the incident occurred:
I was pulling into the gas station driving toward the gas pump when I saw the truck in my mirror about to hit me right where I was sitting. I hit the horn and then the gas and was able to pull forward enough that the impact was to my rear driver's side door and window which shattered.
7. What is the amount of damages claimed arising out of the following circumstances (Include estimates and bills, if available): \$3900 - \$4000

01/22/2009 THU 15:38 FAX 1 509 427 3708 Skamania County Commiss.

0003/003

8. Please list name and address of any and all witnesses or persons involved:

(Please Print)

- Chris Neal 2010 NE 126th Ave, Vancouver, WA 98684 (my passenger)
 - The driver of the truck that hit me, his info is in the police report
 Report # _____; I have now requested twice and have not received.

9. Describe the damages or injuries you sustained as a result of the incident:

My vehicle sustained damage to the driver's side and both my passenger and I have been seeing chiropractors since for back pain.

10. Was incident investigated by a police officer?

Sheriff ☒

State Patrol _____

City _____

Chris Helton

11. If a vehicle was involved in the incident, describe: Make Ford
 Model Explorer Year 2004 State OR License No. VDZ 136
 Insurance Company State Farm Policy Number 91 0859-B19-37

12. Describe what you did after the incident occurred:

Got out to check damage, then waited for police to respond
 gave police description of events and taped up window and
 drove home. Saw doctor for back & neck pain.

13. Describe the conversations you had, if any, with County personnel during or after the incident occurred. He just said he was sorry, he ~~didn't~~ didn't see me and he had to call the police because he was working and then he waited by his vehicle.

14. How did you identify the County as the party responsible for your damage?

The responding officer, Deputy Helton advised me the other driver was at fault and the County was responsible.

I certify under penalty of perjury under the laws of the State of Washington that the information contained in this claim is true and correct.


DATED THIS 27 DAY OF February, 2009


 Claimant's Signature

File Name: Commis/Risk Mang/Claims/Claim For Damages

NOTE: Personal property (car, etc.) damages are to be accompanied by 2 estimates for repair costs. The Skamania County Risk Manager will investigate this claim. The decision to honor this claim will be based upon that investigation. Making a false report or providing false evidence is a crime and punishable by fine and/or imprisonment. Additional pages may be attached if needed to answer the questions.

I got 2 estimates, at Vancouver Auto Group and Bell's Velvet Hammer. The estimate at Bell's was done by the manager, J.D. Hylton and he advised that the vehicle is a total loss and he does not provide a written estimate for that but I am including his contact info, he said to have you contact him and he will provide estimate info over the phone. Thank you.



Bell's Velvet Hammer
J.D. Hylton, Manager
(360) 573-0313
fax (360) 573-8611



Vancouver Auto Group
Ben Ford, Assistant Manager

VANCOUVER AUTO GROUP
 FORD/HYUNDAI/SUZUKI
 6801 NE 40TH ST
 VANCOUVER, WA 98661
 OFFICE: (360) 992-7388 FAX: (360) 992-7364

CD LOG NO 11824-1 DATE 02/16/09

SHOP: VANCOUVER FORD COLLISION
 CITY STATE: VANCOUVER, WA

INSP DATE: 02/16/09
 CONTACT: BEN FORD

OWNER: HARRINGTON, SARAH
 ADDRESS: 3218 NW 122ND ST
 CITY STATE: VANCOUVER, WA
 ZIP: 98685

HOME PHONE: (503) 740-3115

POINT OF IMPACT: 6

LIC#: STATE: VIN: 1FMDU35P0TUC60792
 BODY COLOR: MILEAGE:
 CONDITION: ACCTNG CTL#:

*=USER-ENTERED VALUE	E=REPLACE OEM	NG=REPLACE NAGS
EC=REPLACE ECONOMY	UE=REPLACE OE SURPLUS	UC=RECONDITIONED PRT
UM=REMAN/REBUILT PRT	EU=REPLACE SALVAGE	EP=REPLACE PXN
OE=REPLACE PXN OE SRPLS	PC=PXN RECONDITIONED	PM=PXN REMAN/REBUILT
TE=PARTL REPL PRICE	ET=PARTL REPL LABOR	IT=PARTIAL REPAIR
I=REPAIR	L=REFINISH	BR=BLEND REFINISH
TT=TWO-TONE	CG=CHIPGUARD	SB=SUBLET
N=ADDITIONAL LABOR	RI=R&I ASSEMBLY	P=CHECK
AA=APPEAR ALLOWANCE	RP=RELATED PRIOR	UP=UNRELATED PRIOR

1996 FORD EXPLORER XLT 4DOOR WAGON 8CYL GASOLINE 5.0
 CODE: P8433B/B OPTNS B/24SPFEBX0IT

OPTIONS:

TWO-STAGE - EXTERIOR SURFACES
 4-WHEEL DRIVE
 POWER DOOR LOCKS
 PRIVACY GLASS
 REAR WIPER
 CRUISE CONTROL

TWO-STAGE - INTERIOR SURFACES
 ELEC REMOTE CONTROL MIRRORS
 POWER WINDOWS
 HEATED TAILGATE GLASS
 TILT STEERING WHEEL

OP	GDE	MC	DESCRIPTION	MFG.PART NO.	PRICE	AJ%	B%	HOURS	R
E	0092	01	STRIPE ASSEMBLY	LT F5TZ7820001BD	53.67			INC	1
RI	0127	01	DEFLECTOR,ROCKER PA	LT R&I ASSEMBLY				0.3	1
BR	0207	13	DOOR SHELL,FRONT	LT BLEND REFINISH				2.1	4
				1.0 BLEND					
				0.6 TWO STAGE SETUP					
				0.5 TWO STAGE					
RI	0351		W/STRIP,BELT OUTER L/F	R&I ASSEMBLY				0.2	1
RI	0231		PNL,INNER DOOR TRIM	LT R&I ASSEMBLY				INC	1

1996 FORD EXPLORER XLT 4DOOR WAGON
CD LOG NO 11824-1

E 0243	01	MLDG, FRONT DOOR LOW LT	1L2Z7820879ABPTM	110.37	0.6	1
L 0243		MLDG, FRONT DOOR LOW LT	REFINISH		0.4	4
			0.3 SURFACE			
			0.1 TWO STAGE			
ET0237		STRIPE, FRONT DOOR U LT	LABOR/PARTL REPLA		0.4	1
RI0229		MIRROR, OUTER R/C LT	R&I ASSEMBLY		0.3	1
RI0138		PAD, KEYLESS ENTRY LT	R&I ASSEMBLY		0.8	1
RI0227		HANDLE, FRONT DOOR O LT	R&I ASSEMBLY		0.2	1
E 0287	#	DOOR SHELL, REAR LT	F57Z7824631A	1,285.93	4.1	1
		# = 01, 02				
L 0287		DOOR SHELL, REAR LT	REFINISH		3.4	4
			1.8 SURFACE			
			1.0 EDGE			
			0.6 TWO STAGE			
E 0357		W/STRIP, BELT OUTER LT	F77Z7825597AAA	35.27	INC	1
E 0325	#	MLDG, REAR DOOR LOWE LT	F77Z7825557BAA	65.87	0.6	1
		# = 01, 02				
L 0325		MLDG, REAR DOOR LOWE LT	REFINISH		0.4	4
			0.3 SURFACE			
			0.1 TWO STAGE			
E 0307	#	PNL, INNER DOOR TRIM LT	F5TZ7827407AAZ	321.05	INC	1
		# = 01, 02				
ET0313		STRIPE, REAR DOOR UP LT	LABOR/PARTL REPLA		0.3	1
E 0295		GLASS, REAR DOOR T LT	F1TZ7825713B	163.27	INC	1
E 0276	02	VENT GLS ASSEMBLY, R LT	F5TZ7825767B	259.38	INC	1
RI0305		HANDLE, RR DOOR OUTE LT	R&I ASSEMBLY		INC	1
BR0389		PANEL, QUARTER LT	BLEND REFINISH		1.3	4
			0.9 BLEND			
			0.4 TWO STAGE			
RI0371		MLDG, QUARTER LOWER L/R	R&I ASSEMBLY		0.3	1
ET0274		STRIPE, QUARTER UPPE LT	LABOR/PARTL REPLA		0.4	1
RI0395		QTR GLASS R & I LT	R&I ASSEMBLY		2.1	1
EC0434		SEALANT KIT, QTR GLA LT	ECONOMY PART	18.00*	INC	1
RI0533		TAILLAMP ASSEMBLY LT	R&I ASSEMBLY		0.2	1
L M03		FLEX ADDITIVE	REFINISH	15.00*		*4*
L M14		CORROSION PROTECTION	REFINISH	10.00*	0.4	*4*
L M17		COVER CAR EXTERIOR	REFINISH	10.00*	0.3	*4*
SBM60		HAZARD. WSTE. REM.	SUBLET REPAIR	10.00*		*1*
L		MASK JAMBS	REFINISH		0.3	*4*
I		GLASS CLEAN UP	REPAIR		1.0	*1*

33 ITEMS

MC MESSAGE(S)

01 CALL DEALER FOR EXACT PART NUMBER / PRICE

02 PART NO. DISCONTINUED, CALL DEALER FOR EXACT PART NO

13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

FINAL CALCULATIONS & ENTRIES

GROSS PARTS	2,294.81
OTHER PARTS	53.00
PAINT MATERIAL	258.00

1996 FORD EXPLORER XLT 4DOOR WAGON
CD LOG NO 11824-1

PARTS & MATERIAL TOTAL		2,605.81
TAX ON PARTS & MATERIAL @	8.200%	213.68

LABOR	RATE	REPLACE HRS	REPAIR HRS	
1-SHEET METAL	50.00	10.8	1.0	590.00
2-MECH/ELEC	88.20			
3-FRAME	60.00			
4-REFINISH	50.00	8.6		430.00
5-PAINT MATERIAL	30.00			
LABOR TOTAL				1,020.00
TAX ON LABOR	@		8.200%	83.64
SUBLET REPAIRS				10.00
TAX ON SUBLET	@		8.200%	0.82
TOWING				
STORAGE				

GROSS TOTAL 3,933.95

NET TOTAL 3,933.95

SHOPLINK U2698 ES CD LOG 11824-1 DATE 02/16/09 01:51:22PM R6.37 CD 11/08
PXN: Y/00/00/00/00 CUM 00/00/00/00/00 GEOCODE 98661
HOST LOG
(C) 1998 - 2008 AUDATEX NORTH AMERICA, INC.

2.3 HRS WERE ADDED TO THIS EST. BASED ON AUDATEX TWO-STAGE REFINISH FORMULA.

ESTIMATE IS SUBJECT TO PARTS PRICE INVOICES AT TIME OF REPAIRS.
ADDITIONAL DAMAGES MAY BE DISCOVERED AFTER DISASSEMBLY.

Sarah Harrington
3218 NW 122nd St.
Vancouver, WA 98685

PORTLAND OR 972

06 MAR 2009 PM 1 T



Skamania County Auditor
Skamania County Courthouse
PO Box 790
240 NW Vancouver Avenue, Room 27
Stevenson, WA 98648

98648+0790

