SURVEY NARRATIVE:

THE PURPOSE OF THIS SURVEY IS TO POST THE BOUNDARY OF NATIONAL FOREST SYSTEM LANDS FOR PROJECT CRG2021_01. ALUMINUM POSTS WITH PROPERTY BOUNDARY SIGNS #54-2 WERE SET AT APPROXIMATELY 150-FOOT INTERVALS ALONG THE BOUNDARY. TREES WITHIN 3 FT OF LINE WERE BLAZED, ONE BLAZE ON PRIVATE LAND AND TWO ON FOREST SERVICE LAND. TREES ON LINE WERE TRIPLE BLAZED.

MONUMENTS FROM SR1 AND SR3 WERE FOUND AND HELD FOR THE BOUNDARY SOLUTION. SR1 MONUMENTS AND LINES WERE FOUND CLEARLY POSTED WITH YELLOW CARSONITE POSTS READING "US FISH AND WILDLIFE SERVICE." SR3 MONUMENTS WERE FOUND NEXT TO STEEL T-POSTS AND LINES WERE CONSPICUOUSLY MARKED WITH T AND ANGLE IRON POSTS

METHOD OF SURVEY:

CONTROL POINTS WERE RECOVERED FROM A PREVIOUS PROJECT, CONTRACT AWARD #1205G119F0020 (SEE SR2). A TRAVERSE WAS CONDUCTED BY E. LAMB, PLS ASSISTED BY J. BESANCON, PLS AND D. LONDEN BEGINNING AT EXISTING CONTROL NETWORK POINTS NEAR THE EAST 1/4 CORNER OF SECTION 27, AND PROCEEDING WEST, SOUTH, AND SOUTHEAST AROUND THE BOUNDARY. SAID TRAVERSE CLOSED ON CONTROL NETWORK POINTS NEAR THE SOUTHERLY END OF THE POSTING LIMITS. FOUND MONUMENTS WERE TIED RADIALLY THEREFROM. MEASUREMENTS WERE MADE USING A 3-SECOND TRIMBLE S7 TOTAL STATION WITH EDM (1MM+2PPM). THE TRAVERSE WAS ADJUSTED IN TRIMBLE BUSINESS CENTER BY COMPASS RULE. ALL WORK EXCEEDED THE STANDARDS SET FORTH IN WAC 332-130-90. SAID MONUMENTS WERE REDUNDANTLY OBSERVED WITH RTK GPS AND CHECKED SATISFACTORILY.

THE NORTHEAST CORNER OF SECTION 27 WAS COMPUTED FROM THE AVERAGE OF TWO CONSECUTIVE 3-MINUTE RTK GPS SESSIONS WITH INDEPENDENT INITIALIZATIONS. BASE CORRECTIONS WERE TRANSMITTED FROM GPS BASE CONTROL POINT #65 RECOVERED FROM SAID PREVIOUS PROJECT (SR2). RTK OBSERVATIONS WERE COLLECTED USING A TRIMBLE R8S BASE AND TRIMBLE R10 ROVER (BOTH 8MM+1PPM RMS). A REDUNDANT TRAVERSE WAS CONDUCTED NORTH FROM SAID EXISTING CONTROL NETWORK POINTS NEAR THE EAST 1/4 CORNER TO THE NORTHEAST CORNER OF SECTION 27 WHICH CHECKED SATISFACTORILY.

BEARING TREES WERE MEASURED WITH STEEL TAPE AND HAND COMPASS (DECLINATION 16°E), MARKED WITH SIGNS #54-3 "BEARING TREE" AND #54-9 "LAND SURVEY MONUMENT," AND PAINTED RED WITH 6" BAND AROUND THE CIRCUMFERENCE.

GROUND DISTANCES ARE SHOWN HEREON. FOR WA SOUTH STATE PLANE GRID DISTANCES, APPLY A COMBINED FACTOR OF 0.9999955248.

SURVEY REFERENCES:

- UNRECORDED SURVEY BY US FISH AND WILDLIFE SERVICE,

M. RICHEY 1987

SR2 - AFN 2020-002384, D. RENTON 2020

SR3 - BOOK 3 OF SHORT PLATS, PAGE 84, R. GLAESER 1985

DEED REFERENCES:

D1 - BOOK 256, PAGE 384 JOHNSON TO UNITED STATES OF

AMERICA 2004

D2 - BOOK 102, PAGE 38 THE TRUST FOR PUBLIC LAND TO UNITED STATES OF AMERICA 1986

REVIEWED BY

SIĞNA TURE

02-22-202

I CERTIFY THAT THIS SURVEY WAS PERFORMED AT THE REQUEST OF THE COLUMBIA RIVER GORGE NATIONAL SCENIC AREA FOREST SUPERVISOR

hrust ("herre SIGNATURE

02-22-201 DATE

RECORD OF SURVEY

LOCATED IN THE COLUMBIA RIVER GORGE NATIONAL SCENIC AREA IN THE NE1/4 NE1/4, SE1/4 NE1/4, SW1/4 NE1/4, NW1/4 SE1/4, NE1/4 SE1/4, AND SE1/4 SE1/4 OF SECTION 27 T3N R9E W.M. SKAMANIA COUNTY, WASHINGTON

SYSTEM LANDS

- PUBLIC

BOUNDARY LINE

FD 5/8" REBAR NO CAP W/

STEEL T-POST IN 6" CONC.

CYLINDER PER SR1

N6895'47"W

FD AND HELD 1/2" REBAR W/ YPC "GLAESER

15024" PER SR3. ALSO FD 1" IP IN 6" CONC.

CYLINDER (ORIGIN UNKNOWN) N66°58'27"W 8.06'

119.59" (119.56' SR1)

FD REBAR W/ 1-1/2" AC

COOK-UNDERWOOD RD.

"USFW 1987" PER SR1

NOT FD

CALC PER SR1

CALC POSITION OF 3-1/2" BC IN

CONC. BLOCK PER SR2. SEE SR2

FOR HISTORY AND ACCESSORIES

√ S88°48'07"E

1312.40'

CALC POSITION OF 5/8" IR NO CAP

PER SR2. SEE SR2 FOR ACCESSORIES

N89°39'00"W

1283.84

FD 5/8" REBAR W/ 3-1/2" AC "FISH AND

FIRMED/STRAIGHTENED IN PLACE. HELD FOR

PUBLIC

FD 5/8" REBAR W/ 3-1/4" AC "US


WILDLIFE SERVICE 1987" PER SR1

DEPT OF INTERIOR FISH AND

CE1/16 CORNER (SEE BT SKETCH RIGHT)

WILDLIFE" PER SR1 UP 2 FT LEANING

SEVERELY SW. TIED AT BASE AND



FD 3-1/2" BC IN ROCK

"CORPS OF ENGINEERS US

ARMY" (SEE BT_SKETCH RIGHT)

FD PIPE W/ 3-1/2" BC "CORPS

1283.82' (1283.84' SR1)

OF ENGINEERS US ARMY" IN

ROCK MOUND. SEE SR2 FOR HISTORY AND ACCESSORIES

TO SECTION COR (2664.86' SR1)

(Sp3)

FD 5/8" REBAR NO CAP

IN 6" CONC. CYLINER ON

- CALC POSITION OF 1/2"

CALC POSITION OF 5/8"

IR W/ 3" AC PER SR2

, IP PER SR2

S00°42'17"W


60.79

N-S FENCELINE


VESSUP.

N68°22°50"W _1

133.27' (133.46' SR3)



BEARING TREES AT CE1/16 CORNER SECTION 27 SCALE 1"=30"



LEGEND:

FOUND AND HELD MONUMENT AS NOTED NOVEMBER-DECEMBER 2020

SCALE 1"=20"

CALCULATED POINT

GLO CORNER FOUND

GLO CORNER CALCULATED

ACALUMINUM CAP

ALUMINUM

AUDITOR'S FILE NUMBER BRASS CAP BC

CALC CALCULATED

CONC. CONCRETE

CTR. CENTER

FDFOUND

IR IRON ROD IRON PIPE


SURVEY REFERENCE NUMBER

YPCYELLOW PLASTIC CAP

RECORD DATA

BASIS OF BEARINGS: N89°39'00"W BETWEEN FD PIPE W/ 3-1/2"

BC AT EAST 1/4 CORNER OF SECTION 27 AND FD 5/8" REBAR W/ 3-1/2" AC AT CENTER EAST 1/16 CORNER SECTION 27. ALL BEARINGS ARE WA STATE PLANE SOUTH ZONE NAD 83 (2011) EPOCH 2010 W/ CONVERGENCE ANGLE OF -00°50'15"





UNITED STATES DEPARTMENT OF AGRICULTURE FOREST SERVICE- REGION 6

SURVEYOR'S CERTIFICATE

THIS MAP CORRECTLY REPRESENTS A SURVEY MADE BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE REQUIREMENTS OF THE SURVEY RECORDING ACT AT THE REQUEST OF THE COLUMBIA RIVER GORGE NATIONAL SCENIC AREA IN DECEMBER 2020.

Errille Dans ERIELLE F. LAMB, PLS #20100531 2/22/2021 DATE

S88'49'48"E

1312.90'



SCALC POSITION OF

CALC PER SR2

3/4" IP PER SR2

AUDITOR'S CERTIFICATE

FILED FOR RECORD THIS 22 DAY OF FLOWING 2021 AT SHPM. IN BOOK - OF - AT PAGE AT THE REQUEST OF ERIELLE F. LAMB, PLS.

AFN-2021-COUNTY AUDITOR - DAPUTU

DRAWN BY: JMB CALC BY: JMB CHECK BY: EFL

SHEET 1 OF 1

COLUMBIA LANDS ZONE 987 McCLELLAN ROAD VANCOUVER, WA 98661