Skamania County, WA Total:\$0.00 LCR

2023-001831

12/13/2023 02:55 PM

Pgs=3 Request of: ERIELLE LAMB

00017518202300018310030033

RETURN TO: Erielle Lamb 987 McClellan Road Vancouver, WA 98661


LAND CORNER RECORD

THIS FORM IS FOR RECORDING A PLSS CORNER MONUMENT AND ACCESSORY INFORMATION WHEN A RECORD OF SURVEY IS NOT REQUIRED, PER RCW 58.09.040(2). (UPDATED 8/01/2019. DO NOT REVISE THIS FORM)

CERTIFICATE: THIS LAND CORNER RECORD CORRECTLY REPRESE WORK PERFORMED BY ME OR UNDER MY DIRECTION IN CONFORM.	MANCE
WITH THE SURVEY RECORDING ACT.	
GRANTOR: Erielle Lamb	PAIELLE F. CALLEL OF WASHINGTON
SIGNATURE: Euille nu	SIGNATURE/DATE SIGNAT
CERTIFICATE NO.: 20100531	I TURI
ADDRESS: 987 McClellan Road	DLENIS PRO 20100531
Vancouver, WA 98661	ONAL LAND TO STERED SHE AND STATE OF THE PROPERTY OF THE PROPE
GRANTEE: PUBLIC	The Committee of the Co
INDEXING INFORMATION: 1/41/4SEC: 3	TWP: 4N RGE: 9E
CORNER CODE, SEE DIAGRAM BELOW: D 16-17	
ADDITIONAL IDENTIFIER: (PLSS CORNER NAME) C-W-E-SE	
WPCS: N: E:	
ZONE: DATE OF OBSERVATION: 10/30/2023	
BLM GCDB POINT IDENTIFIER (OPTIONAL): 465620	

PROVIDE THE FOLLOWING INFORMATION ON ATTACHMENTS, AS REQUIRED BY RCW 58.09.060(2)

(a) AN ACCURATE DESCRIPTION AND LOCATION, IN REFERENCE TO THE CORNER POSITION, OF ALL MONUMENTS AND ACCESSORIES FOUND AT THE CORNER; (b) AN ACCURATE DESCRIPTION AND LOCATION, IN REFERENCE TO THE CORNER POSITION, OF ALL MONUMENTS AND ACCESSORIES PLACED OR REPLACED AT THE CORNER; (c) BASIS OF BEARINGS USED TO DESCRIBE OR LOCATE SUCH MONUMENTS OR ACCESSORIES; (d) COROLLARY INFORMATION THAT MAY BE HELPFUL TO RELOCATE OR IDENTIFY THE CORNER. POSITION.



PAGE 1 OF 3

LAND CORNER RECORD ATTACHMENT

CORNER INFORMATION: DISCUSS THE HISTORY, EVIDENCE FOUND, AND PERPETUATION OF THE CORNER. SHOW THE REFERENCES; PROVIDE THE DATE OF THE FIELD WORK; IF APPLICABLE, MAKE REFERENCE TO A MAP OF RECORD AND/OR THE FIELD BOOK/PAGE NO. USE ADDITIONAL SHEETS AS NEEDED.

History:

(1987)- Roy Gaylord (WA PLS#16337) of Terra Surveying in July 1987, set standard 2-1/2"x30" Forest Service Aluminum Pipe and Cap, 24" in the ground for the C-W-E-SE 1/256 corner of section 3, recorded in Skamania land corner record #104135, book 4 of 9, pg 99, from which bears:

15" Douglas Fir, N 5°45' W, 33.0' distance, scribed "S3 1/256BT".

9" Douglas Fir, S 89°45' E, 6.7' distance, scribed "S3 1/256BT".

Trees have red painted bands, 54-3 and 54-9 tags and "PLS 18731" washers. Set carsonite guard post near monument. This monument was set during the Salmon Cadastral Survey as recorded in Book 2 of Surveys, Pages 265-267, Skamania County Auditor's Office.

(2023)- R. Ellis of USDA Forest Service, Columbia Lands Zone on 10/30/2023 recovered the C-W-E-SE 1/256 corner to section 3 as set in July 1987 by Roy Gaylord of Terra Surveying. 6" red bands were painted on all new and old bearing trees.

Evidence:

Found 2-1/2" Aluminum Cap on 2-1/2" Aluminum Pipe, 3-1/2" above the ground. The following bearing objects were recovered:

A 25" Douglas Fir, bears N 5°45' W, 33.0' distance with healed blaze.

A 15" Fir Snag, bears N 89°45' W, 6.7' distance with healed blaze.

Perpetuation:

Unrecorded 20" Douglas Fir, bears \$ 73° E, 38.85' distance, with healed blaze.

Set guard posts 5' East of monument with property boundary and LSM signs attached.

