Total:\$0.00 LCR Pgs=3

Skamania County, WA 2023-001832 12/13/2023 02:55 PM

Request of: ERIELLE LAMB

00017519202300018320030030

RETURN TO: Erielle Lamb 987 McClellan Road Vancouver, WA 98661


LAND CORNER RECORD

THIS FORM IS FOR RECORDING A PLSS CORNER MONUMENT AND ACCESSORY INFORMATION WHEN A RECORD OF SURVEY IS NOT REQUIRED, PER RCW 58.09.040(2). (UPDATED 8/01/2019. DO NOT REVISE THIS FORM)

CERTIFICATE: THIS LAND CORNER RECORD CORRECTLY REPRESENTS WORK PERFORMED BY ME OR UNDER MY DIRECTION IN CONFORMANCE RIELLE WITH THE SURVEY RECORDING ACT. TE OF GRANTOR: Erielle Lamb SEAL/SIGNATURE/DATE SIGNATURE: Eurle **CERTIFICATE NO.:** 20100531 ADDRESS: 987 McClellan Road 7.7.782 Vancouver, WA 98661 LAND D. **GRANTEE: PUBLIC** _SEC:_10 TWP: 4N _RGE:_9**E INDEXING INFORMATION: 1/4** 1/4 corner code, see diagram below: E-F 16-17 ADDITIONAL IDENTIFIER: (PLSS CORNER NAME) C-W-NE-NE 1/256 WPCS: N:_ DATE OF OBSERVATION: 11/27/2023 ZONE: BLM GCDB POINT IDENTIFIER (OPTIONAL): 465570

PROVIDE THE **FOLLOWING INFORMATION ON** ATTACHMENTS, AS **REQUIRED BY** RCW 58.09.060(2)

(a) AN ACCURATE DESCRIPTION AND LOCATION, IN REFERENCE TO THE CORNER POSITION, OF ALL MONUMENTS AND ACCESSORIES FOUND AT THE CORNER; (b) AN ACCURATE DÉSCRIPTION AND LOCATION, IN REFERENCE TO THE CORNER POSITION, OF ALL MONUMENTS AND ACCESSORIES PLACED OR REPLACED AT THE CORNER: (c) BASIS OF BEARINGS ÙŚED TO DESCRIBE OR LOCATE SUCH MONUMENTS OR ACCESSORIES; (d) COROLLARY **INFORMATION THAT MAY** BE HELPFUL TO RELOCATE OR IDENTIFY THE CORNER. POSITION.



PAGE 1 OF 3

LAND CORNER RECORD ATTACHMENT

CORNER INFORMATION: DISCUSS THE HISTORY, EVIDENCE FOUND, AND PERPETUATION OF THE CORNER. SHOW THE REFERENCES; PROVIDE THE DATE OF THE FIELD WORK; IF APPLICABLE, MAKE REFERENCE TO A MAP OF RECORD AND/OR THE FIELD BOOK/PAGE NO. USE ADDITIONAL SHEETS AS NEEDED.

History:

(1987)- Roy Gaylord (WA PLS#16337) of Terra Surveying in July 1987, set standard 2-1/2"x30" Forest Service Aluminum Pipe and Cap, 24" in the ground for the C-W-NE-NE 1/256 corner of section 10, recorded in Skamania County land corner record #104150, book 4 of 9, pg 107, from which bears:

17" Douglas Fir, N 10°15' E, 12.7' distance, scribed "S10 1/256BT".

14" Douglas Fir, S 54°30' W, 13.7' distance, scribed "S10 1/256BT".

Trees have red painted bands, tags and brass "PLS 18731" washers. Set carsonite guard post near monument. This monument was set during the Salmon Cadastral Survey as recorded in Book 2 of Surveys, Pages 265-267, Skamania County Auditor's Office.

(2023)- R. Ellis of USDA Forest Service, Columbia Lands Zone on 11/27/2023 recovered the C-W-NE-NE 1/256 corner to section 10 as set in July 1987 by Roy Gaylord of Terra Surveying. 6" red bands were painted on all new and old bearing trees.

Evidence:

Found 2-1/2" Aluminum Cap on 2-1/2" Aluminum Pipe, 2" above the ground. The following bearing objects were recovered:

A down/dead fir, bears N 10°15' E, 12.7' distance with bt tag attached and old orange paint visible.

A dead/down fir, bears S 54°30' W, 13.7' distance with bt tag attached.

Corner lies along river flat approximately 500' East of the Oklahoma Road.

Perpetuation:

New 22" Douglas Fir, bears S 84° W, 39.45' distance, scribed "S10 1/256BT" with WA PLS#20100531 2" diameter brass washer set right side center from the monument 1.5' high.

New 26" Douglas Fir, bears S 10° E, 48.98' distance, scribed "S10 1/256BT" with WA PLS#20100531 2" diameter brass washer set left side center from the monument 2.3' high.

Set guard posts 5' West and South of monument with property boundary and LSM signs attached.

PAGE 2 OF 3

LAND CORNER RECORD ATTACHMENT **CORNER INFORMATION:** DISCUSS THE HISTORY, EVIDENCE FOUND, AND PERPETUATION OF THE CORNER. SHOW THE REFERENCES; PROVIDE THE DATE OF THE FIELD WORK; IF APPLICABLE, MAKE REFERENCE TO A MAP OF RECORD AND/OR THE FIELD BOOK/PAGE NO. USE ADDITIONAL SHEETS AS NEEDED. Down/Dead Fir S84°W 39.45 New 22" Douglas Fir Down/Dead Fi 48.98 New 26" Douglas Fir PAGE<u>3</u> OF <u>3</u>