Skamania County, WA Total:\$0.00 LCR

2024-000863 07/03/2024 09:23 AM

Pgs=3
Request of: ERIELLE LAMB

00018830202400008630030035

RETURN TO: Erielle Lamb 987 McClellan Road Vancouver, WA 98661


## LAND CORNER RECORD

THIS FORM IS FOR RECORDING A PLSS CORNER MONUMENT AND ACCESSORY INFORMATION WHEN A RECORD OF SURVEY IS NOT REQUIRED, PER RCW 58.09.040(2). (UPDATED 8/01/2019. DO NOT REVISE THIS FORM)

CERTIFICATE: THIS LAND CORNER RECORD CORRECTLY REPRESENTS annamman B WORK PERFORMED BY ME OR UNDER MY DIRECTION IN CONFORMANCE RIELLE WITH THE SURVEY RECORDING ACT. GRANTOR: Erielle Lamb SAUCTON SEAL/SIGNATURE/DATE SIGNATURE: Little Zuw CERTIFICATE NO.: 20100531 SIR NO. ADDRESS: 987 McClellan Road PEGISTERED Vancouver, WA 98661 OVAL Manna **GRANTEE: PUBLIC** SEC: 3 & 2 TWP: 4N RGE: 9E **INDEXING INFORMATION: 1/4** 1/4 CORNER CODE, SEE DIAGRAM BELOW: CD-17 ADDITIONAL IDENTIFIER: (PLSS CORNER NAME) S-N-S 1/256 of S3 & S2 WPCS: N: DATE OF OBSERVATION: 5/15/2024 BLM GCDB POINT IDENTIFIER (OPTIONAL): 500625

#### PROVIDE THE FOLLOWING INFORMATION ON ATTACHMENTS, AS REQUIRED BY RCW 58.09.060(2)

(a) AN ACCURATE DESCRIPTION AND LOCATION, IN REFERENCE TO THE CORNER POSITION, OF ALL MONUMENTS AND ACCESSORIES FOUND AT THE CORNER; (b) AN ACCURATE DESCRIPTION AND LOCATION, IN REFERENCE TO THE CORNER POSITION, OF ALL MONUMENTS AND ACCESSORIES PLACED OR REPLACED AT THE CORNER; (c) BASIS OF BEARINGS USED TO DESCRIBE OR LOCATE SUCH MONUMENTS OR ACCESSORIES; (d) COROLLARY INFORMATION THAT MAY BE HELPFUL TO RELOCATE OR IDENTIFY THE CORNER. POSITION.



PAGE 1 OF 3

# LAND CORNER RECORD ATTACHMENT

**CORNER INFORMATION:** DISCUSS THE HISTORY, EVIDENCE FOUND, AND PERPETUATION OF THE CORNER. SHOW THE REFERENCES; PROVIDE THE DATE OF THE FIELD WORK; IF APPLICABLE, MAKE REFERENCE TO A MAP OF RECORD AND/OR THE FIELD BOOK/PAGE NO. USE ADDITIONAL SHEETS AS NEEDED.

## History:

(1987)- Roy Gaylord (WA PLS#16337) of Terra Surveying in July 1987, set standard 2-1/2"x30" Forest Service Aluminum Pipe and Cap, 24" in the ground for the S-N-S 1/256 corner of section 3 and section 2, recorded in Skamania County land corner record #104125, book 4 of 9, pg 89, from which bears:

12" Red Alder, S57°15'W, 12.7' distance, bark scribed "S3 1/256BT".

9" Red Alder, S2°30'E, 20.4' distance, bark scribed "S2 1/256BT".

Trees have red painted bands, tags and brass "PLS 18731" washers. Set carsonite quard post near monument.

(2024)- R. Ellis of USDA Forest Service, Columbia Lands Zone on 5/15/2024 recovered the S-N-S 1/256 corner to section 3 and section 2 as set in July 1987 by Roy Gaylord of Terra Surveying. 6" red bands were painted on all new and old bearing trees.

#### Evidence:

Found 2-1/2" Aluminum Cap on 2-1/2" Aluminum Pipe, 3-1/2" above the ground. The following bearing objects were recovered:

A 13" Alder, bears N2°30'E, 20.4' distance with healed blaze.

The southwest bearing tree is gone. Found LSM sign stuck in mud near old stump.

Corner lies in a swampy river flat approximately 200' north of the Little White Salmon River.

### Perpetuation:

New 14" Alder, bears S38°W, 24.29' distance measured to 2.5" long magnail set right side center of the tree from the monument, with 2" diameter brass washer marked "WA PLS#20100531" fastened 1.5' above the ground. Tree is scribed "XBT".

Set guard posts 5' South and East of monument with property boundary and LSM signs attached.

PAGE\_2\_OF\_3

